

As of 16-Dec-07

Serial Number Listing

Total Records: 879

| LIN | FSC | NIIN | MODEL | SN | REGNO | YR MFG | STATUS |
|--------|------|-----------|------------|-----------|-----------|--------|--------|
| X40931 | 2320 | 000508905 | M813A1 W/W | 10152 | 5D72371 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | 11764 | 7TAA | 1968 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | 12511259 | 9635778 | 1978 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | 5B57971 | C13510001 | 1996 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | 5C85171 | 5C85171 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | 98293 | 5E14371 | 1986 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C12510743 | 5C23470 | 1970 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C12510831 | 5C32170 | 1970 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C12510850 | 5C51670 | 1970 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C12511161 | 5D34870 | 1979 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C12511659 | 5F2007 | 1970 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C12511738 | NL0Z6N | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C12512390 | 5A44171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13510012 | 5C21171 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13611166 | NL02VP | 1984 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C137 | | | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710001 | 5C14571 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710002 | 5C14971 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710003 | 5C15371 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710004 | 5C15771 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710005 | | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710006 | 5C16471 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710007 | 5C16571 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710008 | 5C16871 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710009 | 5C16971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710010 | 5C17071 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710011 | 5C17171 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710012 | 5C21271 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710013 | 5C21371 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710014 | 5C21671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710015 | 5C21971 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710016 | 5C22171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710017 | 5C22471 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710018 | 5C22771 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710019 | 5C22971 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710021 | 5C23471 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710023 | 5C29371 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710024 | 5C29571 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710025 | 5C29771 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710026 | 5C29871 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710027 | 5C30071 | 1968 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710028 | 5C30271 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710029 | 5C30371 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C13710030 | 5C30571 | 1971 | H |

| | | | | | | | | |
|--------|------|-----------|--------|-----|-----------|---------|------|---|
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710031 | 5C30771 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710032 | 5C36571 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710033 | 5C36671 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710034 | 5C36771 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710035 | 5C36971 | 1970 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710036 | 5C37071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710038 | 5C37471 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710039 | 5C37571 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710040 | 5C37771 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710041 | 5C37971 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710042 | 5C55371 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710043 | 5C55671 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710044 | 5C55971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710045 | 5C56171 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710046 | 5C56471 | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710047 | 5C56771 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710048 | 5C56971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710050 | 5C57571 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710051 | 5C57771 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710052 | 5C60971 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710053 | NL1D2T | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710054 | 5C61171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710055 | | 1970 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710056 | 5C61471 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710057 | 5C61571 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710058 | 5C61771 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710059 | 5C61871 | 1970 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710060 | 5C61971 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710063 | 5C62371 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710064 | 5C62571 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710065 | 5C62671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710066 | 5C75871 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710067 | 5C76171 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710068 | 5C76471 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710069 | 5C76771 | 1976 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710071 | 5C77371 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710072 | 5C77671 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710073 | 5C77971 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710074 | | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710075 | 5C78271 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710076 | 5C84371 | 1968 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710078 | 5C84871 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710079 | | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710080 | 5C85371 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710081 | 5C85671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710082 | 5C85771 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710083 | 5C85971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710084 | 5C94971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710085 | 5C86171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710086 | 5C86371 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710088 | 5C93171 | 1970 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710089 | 5C93471 | 1971 | H |

| | | | | | | | | |
|--------|------|-----------|--------|-----|-----------|---------|------|---|
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710090 | 5C93771 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710091 | 5C94071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710093 | 5C94671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710095 | 5C95271 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710096 | | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710097 | 5D38371 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710098 | 5D38671 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710099 | 5D38971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710100 | 5D39171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710101 | 5D39471 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710102 | 5D39771 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710103 | 5D39971 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710104 | 5D48971 | 1970 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710105 | 5D49071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710106 | 5D49171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710107 | 5D49371 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710108 | 5D49471 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710109 | 5D49571 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710110 | 5D49771 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710111 | 5D49871 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710112 | 5D49971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710113 | 5D50171 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710114 | 5D50271 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710115 | 5D50371 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710116 | 5D50571 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710117 | 5D50671 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710118 | 5D50771 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710119 | 5D50971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710120 | 5D51071 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710121 | 5D51171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710122 | 5D51371 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710123 | 5D51471 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710124 | 5D51571 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710125 | 5D51771 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710126 | 5D51871 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710129 | 5D52271 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710130 | 5D52371 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710131 | 5D52571 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710132 | 5D52671 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710133 | 5D52771 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710134 | 5D52971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710136 | 5D53171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710137 | 5D53371 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710138 | 5D53471 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710139 | 5D53571 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710140 | 5D53771 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710141 | 5D53871 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710142 | 5D53971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710143 | 5D54171 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710144 | 5D54271 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710145 | | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710146 | 5D54571 | 1971 | C |

| | | | | | | | | |
|--------|------|-----------|--------|-----|-----------|---------|------|---|
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710147 | 5D54671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710148 | | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710149 | 5D71571 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710150 | 5D71871 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710151 | 5D72071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710153 | 5D72671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710154 | 5D72871 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710155 | 5D73171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710156 | 5D73471 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710157 | 5D73671 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710158 | 5D73971 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710159 | 5D74271 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710160 | 5D74471 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710161 | 5D74771 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710162 | 5D78471 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710163 | 5D78771 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710164 | 5D78971 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710165 | 5D79271 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710166 | 5D79571 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710167 | 5D79771 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710168 | 5D80071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710169 | 5D80371 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710170 | 5D80571 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710171 | 5D80871 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710172 | 5D81171 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710173 | 5D81371 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710174 | 5D81671 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710175 | 5D81971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710176 | 5D82171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710177 | 5D82471 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710178 | 5D82771 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710179 | 5D82971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710180 | 5D83271 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710181 | 5D88171 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710182 | 5D88471 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710183 | 5D88771 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710184 | 5D88971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710185 | 5D89271 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710186 | 5D89571 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710187 | 5D89771 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710188 | 5D90071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710190 | 5E04771 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710191 | 5E05071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710192 | 5E05171 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710193 | 5E05571 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710194 | 5E05871 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710195 | 5E06171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710196 | 5E06371 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710197 | 5E06671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710198 | 5E11171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710199 | 5E11471 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710200 | 5E11771 | 1971 | H |

| | | | | | | | | |
|--------|------|-----------|--------|-----|-----------|---------|------|---|
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710201 | 5E11971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710202 | 5E12271 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710203 | 5E12571 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710204 | 5E12771 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710205 | 5E13071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710206 | 5E13371 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710207 | 5E13571 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710208 | 5E13871 | 1969 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710209 | 5E14171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710210 | | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710211 | 5E14671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710212 | 5E14971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710213 | 5E15171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710214 | 5E15471 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710215 | 5E15771 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710216 | 5E15971 | 1975 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710218 | 5E21671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710219 | 5E21971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710220 | 5E22271 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710221 | 5E22471 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710222 | 5E22771 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710223 | 5E23071 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710224 | 5E23271 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710225 | 5E23571 | 1975 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710226 | 5E29171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710227 | 5E29471 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710228 | 5E29771 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710229 | 5E29971 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710230 | 5E30271 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710231 | 5E30571 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710232 | 5E30771 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710233 | 5E31071 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710234 | 5E31371 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710235 | 5E31571 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710236 | 5E31771 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710237 | 5E31971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710238 | 5E32271 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710239 | 5E32571 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710240 | 5E32771 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710241 | 5E33071 | 1975 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710243 | 5E53071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710244 | 5E53371 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710245 | 5E53571 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710247 | 5E54171 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710248 | 5E57071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710249 | 5E57271 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710250 | 5E57571 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710251 | 5E57871 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710252 | 5E58071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710253 | 5E58371 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710254 | 5E58671 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710255 | 5E58871 | 1971 | H |

| | | | | | | | | |
|--------|------|-----------|--------|-----|-----------|---------|------|---|
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710256 | 5E67771 | 1970 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710257 | 5E68071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710258 | 5E68271 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710259 | 5E68571 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710260 | 5E68871 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710261 | 5E69071 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710262 | 5B69271 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710263 | 5E79371 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710264 | 5E79571 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710265 | 5E79871 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710266 | 5E80171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710267 | 5E80371 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710268 | 5E80671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710269 | 5E80971 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710270 | 5E81171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710271 | 5E81471 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710272 | | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710273 | 5E90371 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710274 | 5E90671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710275 | 5E90971 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710276 | 5E91071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710277 | 5E91171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710278 | 5E91371 | 1970 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710279 | 5E91471 | 1970 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710280 | 5E91571 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710281 | 5E91771 | 1970 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710282 | 5E91871 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710283 | 5E98171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710284 | 5E98371 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710285 | 5E98671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710286 | 5E98971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710287 | 5E99171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710289 | 5E99771 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710290 | 5E99971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710291 | 5F00371 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710292 | 5F00671 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710293 | 5F09471 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710294 | 5F09671 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710295 | 5F09971 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710296 | 5F10271 | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710297 | 5F10471 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710298 | 5F10771 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710299 | 5F11071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710300 | 5F11271 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710301 | 5F11571 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710302 | 5F11871 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710304 | 5F12371 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710305 | 5F12671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710306 | 5F12871 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710307 | 5F13171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710308 | 5F28271 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710309 | 5F28471 | 1971 | H |

| | | | | | | | | |
|--------|------|-----------|--------|-----|-----------|---------|------|---|
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710310 | 5F28771 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710311 | 5F29071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710314 | 5F29671 | | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710315 | 5F29871 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710316 | 5F29971 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710317 | 5F30071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710318 | 5F30271 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710319 | 5F30371 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710321 | 5F30671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710322 | 5F42071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710323 | 5F42271 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710324 | 5F42471 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710325 | 5F42671 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710326 | 5F42871 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710327 | 5F43071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710328 | 5F43271 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710329 | 5F43471 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710330 | 5F43671 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710331 | 5F43871 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710332 | 5F52971 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710333 | 5F53271 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710334 | 5F53571 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710335 | 5F53771 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710336 | 5F54071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710337 | 5F54371 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710338 | 5F54571 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710339 | 5F54871 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710340 | 5F55171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710341 | 5F55371 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710342 | 5F55671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710344 | 5F56171 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710345 | 5F56471 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710347 | 5F56971 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710348 | 5F57271 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710349 | 5F57571 | 1970 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710350 | 5F57771 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710351 | 5F70671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710353 | 5F71071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710354 | 5F71271 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710355 | 5F71471 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710356 | 5F71671 | 1963 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710357 | 5F71871 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710358 | 5F72071 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710359 | 5F72271 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710360 | 5F72471 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710361 | 5F72671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710362 | 5F72871 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710363 | 5F73071 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710364 | 5F73271 | 1970 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710365 | 5F73471 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710367 | 5F73871 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710369 | 5F74271 | 1971 | C |

| | | | | | | | | |
|--------|------|-----------|--------|-----|-----------|---------|------|---|
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710370 | 5F74471 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710371 | 5F74671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710372 | 5F83471 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710373 | 5F83671 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710374 | 5F83871 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710375 | 5F84071 | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710376 | 5F84271 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710377 | 5F84471 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710378 | 5F84671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710379 | 5F84871 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710380 | 5F85071 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710381 | 5F85271 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710382 | 5F85471 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710383 | 5F85671 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710384 | 5F85871 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710385 | 5F86071 | 1969 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710386 | | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710387 | 5F86371 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710388 | | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710389 | | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710390 | 5F86671 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710393 | 5F86971 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710394 | 5F87071 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710396 | NL001L | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710397 | NL001P | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710398 | NL001R | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710399 | NL001U | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710400 | NL001X | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710401 | NL001Z | 1976 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710402 | NL0022 | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710404 | NL0027 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710405 | NL002A | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710407 | NL002F | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710408 | NL002J | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710409 | NL002M | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710410 | NL002N | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710411 | NL002P | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710412 | NL002R | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710413 | NL002S | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710414 | NL002T | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710415 | NL002V | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710416 | NL002W | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710418 | NL002Z | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710419 | NL0030 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710420 | NL008W | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710421 | NL008Y | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710422 | NL0090 | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710423 | NL0092 | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710424 | NL0094 | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710425 | NL0096 | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710426 | NL0098 | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710427 | NL009A | 1973 | C |

| | | | | | | | | |
|--------|------|-----------|--------|-----|-----------|--------|------|---|
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710428 | NL009C | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710429 | NL009E | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710430 | NL009G | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710431 | NL009J | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710432 | NL009L | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710434 | NL009Q | 1973 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710436 | NL009U | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710437 | NL009W | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710438 | NL009Y | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710440 | NL00A2 | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710441 | NL00A4 | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710442 | NL00A6 | 1976 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710443 | NL00CN | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710445 | NL00CS | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710446 | NL00CU | 1966 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710447 | NL00CW | 1976 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710448 | NL00CY | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710449 | NL00D0 | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710450 | NL00D2 | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710452 | NL00D6 | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710453 | NL00D8 | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710454 | NL00DA | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710456 | NL00FV | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710457 | NL00FX | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710460 | NL00G3 | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710461 | NL00G5 | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710462 | NL00G7 | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710463 | NL00G9 | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710465 | NL00GD | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710466 | NL00GF | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710467 | NL00GH | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710468 | NL00GK | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710469 | NL00GM | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710471 | NL00KC | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710472 | NL00KE | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710475 | NL00KL | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710476 | NL00KN | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710477 | NL00KQ | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710478 | NL00KS | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710480 | NL00KV | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710481 | NL00KW | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710482 | NL00KX | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710483 | NL00KY | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710484 | NL00KZ | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710485 | NL00L0 | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710486 | NL00L1 | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710487 | NL00L2 | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710488 | NL00L3 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710490 | NL00L5 | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710491 | NL00L6 | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710492 | NL00L7 | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710493 | NL00MK | 1972 | H |

| | | | | | | | | |
|--------|------|-----------|--------|-----|-----------|---------|------|---|
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710494 | NL00ML | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710495 | NL00MM | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710497 | NL00WW | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710498 | NL00WX | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710499 | NL00WZ | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710500 | NL00X1 | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710504 | NL00Z0 | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710506 | NL00Z4 | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710507 | NL00Z6 | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710508 | NL00Z8 | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710509 | NL00ZA | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710510 | NL010L | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710511 | NL010N | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710512 | NL010Q | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710513 | NL010S | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710514 | NL010U | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710515 | NL010W | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710516 | NL010Y | 1972 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710517 | NL0110 | 1972 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C13710824 | 5F98371 | 1971 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C17510753 | NL1D1V | 1968 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C1Z510447 | WQ7TAA | | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22810722 | NL06X5 | 1978 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22810913 | NL072S | 1978 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910393 | NL05BE | 1977 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910394 | NL05BF | 1977 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910395 | NL05BG | 1977 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910397 | NL05BJ | 1977 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910398 | NL05BK | | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910399 | NL05BL | 1977 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910400 | NL05BM | 1970 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910401 | NL05BN | | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910402 | NL05BP | | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910465 | NL07B2 | | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910467 | NL07B4 | | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910476 | NL07L6 | 1970 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910477 | NL07L7 | | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910482 | NL07LC | 1979 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910483 | NL07LD | | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910484 | NL07LE | | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910487 | NL07LH | 1979 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910489 | NL07LK | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910491 | NL07LM | | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C22910492 | NL07LN | 1979 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32510207 | NL082H | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32510268 | NL0846 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32510737 | NL088P | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32511003 | NL08JZ | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910001 | NL089B | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910002 | NL089C | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910003 | NL089D | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910004 | NL089E | 1980 | C |

| | | | | | | | | |
|--------|------|-----------|--------|-----|-----------|--------|------|---|
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910005 | NL089F | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910006 | NL089G | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910007 | NL089H | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910008 | NL089J | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910009 | NL089K | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910010 | NL089L | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910011 | NL089M | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910012 | NL089N | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910013 | NL089P | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910014 | NL089Q | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910015 | NL089R | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910016 | NL089S | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910017 | NL089T | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910018 | NL089U | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910019 | NL089V | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910020 | NL089W | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910021 | NL089X | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910022 | NL089Y | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910023 | NL089Z | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910024 | NL08A0 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910025 | NL08A1 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910026 | NL08A2 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910027 | NL08A3 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910028 | NL08A4 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910029 | NL08A5 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910030 | NL08A6 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910031 | NL08A7 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910032 | NL08A8 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910033 | NL08A9 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910034 | NL08AA | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910035 | NL08AB | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910036 | NL08AC | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910037 | NL08AD | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910038 | NL08AE | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910040 | NL0D90 | 1982 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910121 | NL08AG | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910122 | NL08AH | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910123 | NL08AJ | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910124 | NL08AK | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910125 | NL08AL | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910126 | NL08AM | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910127 | NL08AN | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910128 | NL08AP | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910129 | NL08AQ | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910130 | NL08AR | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910131 | NL08AS | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910132 | NL08AT | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910133 | NL08AU | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910134 | NL08AV | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910135 | NL08AW | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910136 | NL08AX | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910137 | NL08AY | 1980 | C |

| | | | | | | | |
|--------|------|-----------|------------|-----------|--------|------|---|
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910138 | NL08AZ | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910139 | NL08B0 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910140 | NL08B1 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910141 | NL08B2 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910142 | NL08B3 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910143 | NL08B4 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910144 | NL08B5 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910145 | NL08B6 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910146 | NL08B7 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910147 | NL08B8 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910148 | NL08B9 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910149 | NL08BA | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910150 | NL08BB | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910151 | NL08BC | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910152 | NL08BD | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910153 | NL08BE | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910154 | NL0893 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910155 | NL0894 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910156 | NL0895 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910157 | NL0896 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910158 | NL0897 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910159 | NL0898 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910160 | NL0899 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910162 | NL08C3 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910163 | NL08C4 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910164 | NL08C5 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910165 | NL08C6 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910166 | NL08C7 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910167 | NL08C8 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910168 | NL08C9 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910169 | NL08CA | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910170 | NL08CB | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910171 | NL08CC | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910172 | NL08CD | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910173 | NL08CE | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910174 | NL08CF | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910175 | NL08CG | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910176 | NL08CH | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910177 | NL08CJ | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910178 | NL08CK | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910179 | NL08CL | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910180 | NL08CM | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910181 | NL08CN | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910182 | NL08CP | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910183 | NL08CQ | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910184 | NL08CR | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910185 | NL08CS | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910186 | NL08CT | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910187 | NL08CU | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910188 | NL08CV | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910189 | NL08CW | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910190 | NL08CX | 1980 | C |

| | | | | | | | |
|--------|------|-----------|------------|-----------|--------|------|---|
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910191 | NL08CY | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910192 | NL08CZ | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910193 | NL08D0 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910194 | NL08D1 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910195 | NL08BF | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910197 | NL08BH | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910198 | NL08BJ | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910199 | NL08BK | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910200 | NL08BL | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910201 | NL08BM | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910202 | NL08BN | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910203 | NL08BP | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910204 | NL08BQ | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910205 | NL08BR | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910206 | NL08BS | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910207 | NL08BT | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910208 | NL08BU | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910209 | NL08BV | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910210 | NL08BW | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910211 | NL08BX | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910212 | NL08BY | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910213 | NL08BZ | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910214 | NL08C0 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910215 | NL08C1 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910216 | NL08C2 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910271 | NL08SE | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910272 | NL08SF | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910274 | NL08SH | | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910275 | NL08SJ | | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910276 | NL08SK | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910277 | NL08SL | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910278 | NL08SM | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910280 | NL08SP | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910283 | NL08NR | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910284 | NL08NS | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910285 | NL08NT | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910286 | NL08NU | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910287 | NL08NV | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910288 | NL08NW | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910289 | NL08NX | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910290 | NL08NY | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910291 | NL08NZ | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910292 | NL08P0 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910293 | NL08P1 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910294 | NL08P2 | | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910295 | NL08P3 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910296 | NL08P4 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910297 | NL08P5 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910298 | NL08P6 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910299 | NL08P7 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910300 | NL08P8 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910301 | NL08P9 | 1980 | C |

| | | | | | | | |
|--------|------|-----------|------------|-----------|--------|------|---|
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910302 | NL08PA | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910305 | NL08PD | 1979 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910306 | NL08PE | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910307 | NL08PF | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910308 | NL08PG | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910309 | NL08PH | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910351 | NL08PJ | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910352 | NL08PK | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910353 | NL08PL | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910354 | NL08PM | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910356 | NL08PP | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910357 | NL08PQ | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910359 | NL08PS | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910360 | NL08PT | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910361 | NL08PU | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910362 | NL08PV | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910363 | NL08PW | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910364 | NL08PX | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910365 | NL08PY | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910366 | NL08PZ | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910367 | NL08Q0 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910368 | NL08Q1 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910369 | NL08Q2 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910371 | NL08Q4 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910372 | NL08Q5 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910373 | NL08Q6 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910374 | NL08Q7 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910375 | NL08Q8 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910376 | NL08Q9 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910377 | NL08QA | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910378 | NL08QB | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910379 | NL08QC | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910380 | NL08QD | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910381 | NL08QE | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910382 | NL08QF | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910384 | NL08QH | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910385 | NL08QJ | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910386 | NL08QK | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910387 | NL08QL | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910388 | NL08QM | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910389 | NL08QN | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910390 | NL08QP | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910391 | NL08QQ | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910392 | NL08QR | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910393 | NL08QS | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910394 | NL08QT | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910395 | NL08QU | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910396 | NL08QV | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910398 | NL08QX | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910399 | NL08QY | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910400 | NL08QZ | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 W/W | C32910401 | NL08R0 | 1980 | C |

| | | | | | | | | |
|--------|------|-----------|--------|-----|-----------|--------|------|---|
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910402 | NL08R1 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910403 | NL08R2 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910404 | NL08R3 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910405 | NL08R4 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910406 | NL08R5 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910407 | NL08R6 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910408 | NL08R7 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910409 | NL08R8 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910411 | NL08RA | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910412 | NL08RB | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910413 | NL08RC | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910414 | NL08RD | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910415 | NL08RE | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910416 | NL08RF | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910417 | NL08RG | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910418 | NL08RH | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910419 | NL08RJ | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910420 | NL08RK | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910421 | NL08RL | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910422 | NL08RM | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910423 | NL08RN | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910424 | NL08RP | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910425 | NL08RQ | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910426 | NL08RR | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910427 | NL08RS | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910428 | NL08RT | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910429 | NL08RU | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910430 | NL08RV | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910431 | NL08RW | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910432 | NL08RX | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910433 | NL08RY | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910434 | NL08RZ | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910435 | NL08S0 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910436 | NL08S1 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910437 | NL08S2 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910438 | NL08S3 | 1980 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910439 | NL08S4 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910440 | NL08S5 | 1980 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910441 | NL08S6 | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910442 | NL08SS | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910443 | NL08ST | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910444 | NL08S7 | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910445 | NL08S8 | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910446 | NL08S9 | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910447 | NL08SA | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910448 | NL08SB | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910449 | NL08SC | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910450 | NL08SD | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910451 | NL08V1 | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910452 | NL08V2 | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910453 | NL08V3 | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910454 | NL08V4 | 1981 | C |

| | | | | | | | | |
|--------|------|-----------|--------|-----|-----------|--------|------|---|
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910456 | NL08V6 | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910457 | NL08V7 | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910458 | NL08V8 | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910459 | NL08V9 | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910460 | NL08VA | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910461 | NL08VB | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910462 | NL08VC | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910463 | NL08VD | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910464 | NL08VE | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910465 | NL08VF | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910466 | NL08VG | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910467 | NL08VH | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910468 | NL08VJ | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910469 | NL08VK | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910470 | NL08VL | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910471 | NL08VM | | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910472 | NL08VN | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910473 | NL08VP | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910474 | NL08VQ | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910475 | NL08VR | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910477 | NL08VT | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910478 | NL08VU | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910479 | NL08VV | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910480 | NL08VW | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910481 | NL08VX | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910482 | NL08VY | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910483 | NL08VZ | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910484 | NL08W0 | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910485 | NL08W1 | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910487 | NL08W3 | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910488 | NL08W4 | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910489 | NL08W5 | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910491 | NL08W7 | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910494 | NL08WA | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910495 | NL08WB | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910496 | NL08WC | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910497 | NL08WD | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910499 | NL08WF | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910500 | NL08WG | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910503 | NL08WK | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910504 | NL08WL | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910505 | NL08WM | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910506 | NL08WN | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910507 | NL08WP | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910508 | NL08WQ | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910509 | NL08WR | | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910510 | NL08WS | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910511 | NL08WT | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910512 | NL08WU | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910513 | NL08WV | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910514 | NL08WW | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910515 | NL08WX | 1981 | C |

| | | | | | | | | |
|--------|------|-----------|--------|-----|-----------|--------|------|---|
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910516 | NL08WY | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910518 | NL08X0 | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910519 | NL08X1 | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910520 | NL08X2 | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910521 | NL08X3 | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910522 | NL08X4 | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910523 | NL08X5 | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910525 | NL08X7 | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910526 | NL08X8 | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910527 | NL08X9 | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910528 | NL08XA | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910530 | NL08XC | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910531 | NL08XD | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910535 | NL08XH | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910536 | NL08XJ | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910537 | NL08XK | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910538 | NL08XL | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910539 | NL08XM | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910540 | NL08XN | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910541 | NL08XP | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910543 | NL08XR | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910548 | NL08XW | | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910549 | NL08XX | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910550 | NL08XY | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910552 | NL08Y0 | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910555 | NL08Y3 | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910556 | NL08Y4 | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910557 | NL08Y5 | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910558 | NL08Y6 | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910560 | NL08Y8 | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910562 | NL08YA | 1978 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910563 | NL08YB | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910564 | NL08YC | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910566 | NL08YE | | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910569 | NL08YH | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910570 | NL08YJ | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910571 | NL08YK | 1973 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910573 | NL08YM | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910574 | NL08YN | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910575 | NL08YP | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910576 | NL08YQ | 1981 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C32910577 | NL08YR | 1981 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C42910016 | NL0D8W | 1971 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C42910033 | NL0D8T | 1982 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C42910034 | NL0D8U | 1982 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C42910035 | NL0D8V | 1982 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C42910037 | NL0D8X | 1982 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C42910038 | NL0D8Y | 1982 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C42910039 | NL0D8Z | 1982 | C |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C42910042 | NL0D92 | 1982 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C42910043 | NL0D93 | 1982 | H |
| X40931 | 2320 | 000508905 | M813A1 | W/W | C42910044 | NL0D94 | 1983 | H |

| | | | | | | | |
|--------|------|-----------|------------|-------------|--------|------|---|
| X40931 | 2320 | 000508905 | M813A1 W/W | C52501537 | NL0F1V | 1984 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | NL08NP10281 | NL08NP | 1979 | C |
| X40931 | 2320 | 000508905 | M813A1 W/W | NL08R910410 | NL08R9 | 1979 | C |