

As of 06-Dec-07

## Serial Number Listing

Total Records: 1316

LIN	FSC	NIIN	MODEL	SN	REGNO	YR MFG	STATUS
X39735	2320	008358322	M37	10294	2384001	1951	C
X39735	2320	008358322	M37	10864	2402822	1951	C
X39735	2320	008358322	M37	12456783	3B1477	1952	C
X39735	2320	008358322	M37	14201	3E4772	1951	H
X39735	2320	008358322	M37	14771	3E5360	1951	H
X39735	2320	008358322	M37	17393	2409247	1953	H
X39735	2320	008358322	M37	2372095	2372095	1951	H
X39735	2320	008358322	M37	2384011	2384011	1951	C
X39735	2320	008358322	M37	2401248	2401248	1951	C
X39735	2320	008358322	M37	2407007	2407007	1951	C
X39735	2320	008358322	M37	2407188	2407188	1951	H
X39735	2320	008358322	M37	2407542	2407542	1951	H
X39735	2320	008358322	M37	2427880	2H10449	1952	H
X39735	2320	008358322	M37	2432133	2432133	1952	H
X39735	2320	008358322	M37	2434354	2434354	1952	H
X39735	2320	008358322	M37	2437112	2437112	1952	H
X39735	2320	008358322	M37	2439974	2439974	1952	H
X39735	2320	008358322	M37	2440739	2440739	1953	C
X39735	2320	008358322	M37	2441349	2441349	1952	C
X39735	2320	008358322	M37	2443019	2443019	1952	H
X39735	2320	008358322	M37	260261	2441390	1952	C
X39735	2320	008358322	M37	2650	2384681	1951	C
X39735	2320	008358322	M37	2668158532	3E6539	1951	H
X39735	2320	008358322	M37	30016643	2404712	1951	H
X39735	2320	008358322	M37	30040798	20955757	1952	H
X39735	2320	008358322	M37	30260597	2442327	1954	C
X39735	2320	008358322	M37	38302	242664	1952	C
X39735	2320	008358322	M37	3926	6K9685	1951	H
X39735	2320	008358322	M37	40741	2420931	1952	H
X39735	2320	008358322	M37	41273	2401744	1951	C
X39735	2320	008358322	M37	4189	3D4362	1962	C
X39735	2320	008358322	M37	437048	2437048	1953	C
X39735	2320	008358322	M37	43754	3B3634	1952	C
X39735	2320	008358322	M37	50017282	2409173	1951	C
X39735	2320	008358322	M37	50262187	2442737	1954	H
X39735	2320	008358322	M37	5119	2422950	1967	H
X39735	2320	008358322	M37	52094	2437674	1952	C
X39735	2320	008358322	M37	58584	2440727	1952	H
X39735	2320	008358322	M37	601151	3B7373	1952	C
X39735	2320	008358322	M37	60321	3B7230	1952	C
X39735	2320	008358322	M37	60392	3B7424	1952	C
X39735	2320	008358322	M37	60415	3B7446	1952	C
X39735	2320	008358322	M37	6269	3A8729	1951	C
X39735	2320	008358322	M37	63387	3C1656	1952	C

X39735	2320	008358322	M37	63781	2443816	1952	H
X39735	2320	008358322	M37	66360	3N7954	1952	H
X39735	2320	008358322	M37	664666	21009658	1953	C
X39735	2320	008358322	M37	6795226	2427466	1952	C
X39735	2320	008358322	M37	70007032	2407008	1951	C
X39735	2320	008358322	M37	7581	2440999	1951	C
X39735	2320	008358322	M37	7627	3D7862	1951	H
X39735	2320	008358322	M37	8000047	2406993	1951	C
X39735	2320	008358322	M37	800006236	2371912	1951	C
X39735	2320	008358322	M37	800006330	2371894	1951	C
X39735	2320	008358322	M37	80000708	2406271	1951	C
X39735	2320	008358322	M37	80001207	2406353	1951	H
X39735	2320	008358322	M37	800017793	2410588	1951	H
X39735	2320	008358322	M37	80001831	2410360	1952	H
X39735	2320	008358322	M37	800019455	2410853	1952	H
X39735	2320	008358322	M37	80002194	2412407	1952	H
X39735	2320	008358322	M37	800021987	2421561	1952	H
X39735	2320	008358322	M37	800040356	20955537	1952	C
X39735	2320	008358322	M37	800040694	20955834	1952	H
X39735	2320	008358322	M37	800047573	2433611	1953	H
X39735	2320	008358322	M37	800049370	2434497	1953	C
X39735	2320	008358322	M37	80006019	2406292	1951	H
X39735	2320	008358322	M37	80006084	2407012	1951	C
X39735	2320	008358322	M37	80006097	2371819	1951	H
X39735	2320	008358322	M37	80006110	2406294	1951	C
X39735	2320	008358322	M37	80006119	2407160	1951	C
X39735	2320	008358322	M37	80006127	2371652	1951	H
X39735	2320	008358322	M37	80006137	2407042	1951	C
X39735	2320	008358322	M37	80006138	2407091	1951	H
X39735	2320	008358322	M37	80006145	3C9860	1951	C
X39735	2320	008358322	M37	80006195	2407198	1951	C
X39735	2320	008358322	M37	80006196	2407113	1951	C
X39735	2320	008358322	M37	80006243	2371704	1951	H
X39735	2320	008358322	M37	80006246	2406360	1951	C
X39735	2320	008358322	M37	80006266	2371709	1951	H
X39735	2320	008358322	M37	80006272	2371743	1951	C
X39735	2320	008358322	M37	80006297	2407041	1951	C
X39735	2320	008358322	M37	80006324	2371890	1951	C
X39735	2320	008358322	M37	80006329	2406281	1951	H
X39735	2320	008358322	M37	80006374	2406349	1951	C
X39735	2320	008358322	M37	80006376	2371813	1952	H
X39735	2320	008358322	M37	80006437	2371979	1951	C
X39735	2320	008358322	M37	80006461	2371808	1951	C
X39735	2320	008358322	M37	80006480	2406988	1951	C
X39735	2320	008358322	M37	80006486	2372026	1951	C
X39735	2320	008358322	M37	80006498	2371859	1951	C
X39735	2320	008358322	M37	80006501	2407152	1951	C
X39735	2320	008358322	M37	80006519	2371835	1951	C
X39735	2320	008358322	M37	80006553	2371908	1951	C
X39735	2320	008358322	M37	80006589	2407056	1951	C
X39735	2320	008358322	M37	80006628	2407010	1951	C
X39735	2320	008358322	M37	80006638	2406308	1951	C

X39735	2320	008358322	M37	80006648	2407098	1951	C
X39735	2320	008358322	M37	80006651	2407030	1951	C
X39735	2320	008358322	M37	80006657	2371953	1951	H
X39735	2320	008358322	M37	80006692	2371937	1951	C
X39735	2320	008358322	M37	80006695	2406377	1951	C
X39735	2320	008358322	M37	80006704	2407044	1951	H
X39735	2320	008358322	M37	80006722	2407116	1951	C
X39735	2320	008358322	M37	80006745	2407031	1951	C
X39735	2320	008358322	M37	80006747	2407162	1951	C
X39735	2320	008358322	M37	80006793	2407100	1951	C
X39735	2320	008358322	M37	80006811	2407004	1951	C
X39735	2320	008358322	M37	80006813	2407164	1951	C
X39735	2320	008358322	M37	80006820	2406996	1951	C
X39735	2320	008358322	M37	80006836	2406330	1951	C
X39735	2320	008358322	M37	80006863	2407163	1951	H
X39735	2320	008358322	M37	80006873	2406354	1951	C
X39735	2320	008358322	M37	80006874	2406289	1951	C
X39735	2320	008358322	M37	80006901	2407084	1951	C
X39735	2320	008358322	M37	80006920	2406995	1951	C
X39735	2320	008358322	M37	80006926	2407055	1951	H
X39735	2320	008358322	M37	80006933	2407124	1951	C
X39735	2320	008358322	M37	80006959	2407080	1951	C
X39735	2320	008358322	M37	80006978	2406286	1951	C
X39735	2320	008358322	M37	80006979	2406334	1951	H
X39735	2320	008358322	M37	80006990	2406320	1951	C
X39735	2320	008358322	M37	80007023	2407147	1951	C
X39735	2320	008358322	M37	80007026	2407166	1951	C
X39735	2320	008358322	M37	80007030	2407095	1951	C
X39735	2320	008358322	M37	8000704	2407109	1951	C
X39735	2320	008358322	M37	80007042	2407161	1951	C
X39735	2320	008358322	M37	80007078	2407072	1951	C
X39735	2320	008358322	M37	8000709024	6365	1951	H
X39735	2320	008358322	M37	80007092	2406293	1951	C
X39735	2320	008358322	M37	80007093	2407129	1951	C
X39735	2320	008358322	M37	8000710	2371711	1951	C
X39735	2320	008358322	M37	80007114	2407101	1951	H
X39735	2320	008358322	M37	80007137	2407137	1951	C
X39735	2320	008358322	M37	80007139	2371923	1951	H
X39735	2320	008358322	M37	8000716	2406413	1951	H
X39735	2320	008358322	M37	80007171	2407191	1951	C
X39735	2320	008358322	M37	80007172	2407135	1951	C
X39735	2320	008358322	M37	80007190	2406992	1951	C
X39735	2320	008358322	M37	80007200	2406301	1951	H
X39735	2320	008358322	M37	80007210	2406423	1951	H
X39735	2320	008358322	M37	80007211	2406384	1951	H
X39735	2320	008358322	M37	80007234	2406391	1951	C
X39735	2320	008358322	M37	80007239	2406439	1951	H
X39735	2320	008358322	M37	80007240	2406444	1951	H
X39735	2320	008358322	M37	80007248	2406425	1951	H
X39735	2320	008358322	M37	80007249	2406456	1951	C
X39735	2320	008358322	M37	8000725	2406402	1951	H
X39735	2320	008358322	M37	80007251	2406443	1951	C

X39735	2320	008358322	M37	80007256	2406429	1951	H
X39735	2320	008358322	M37	80007269	2406458	1951	H
X39735	2320	008358322	M37	80007271	2406449	1951	H
X39735	2320	008358322	M37	80007283	2406488	1951	H
X39735	2320	008358322	M37	80007285	2406452	1951	H
X39735	2320	008358322	M37	80007288	2406442	1951	H
X39735	2320	008358322	M37	80007325	2406184	1951	C
X39735	2320	008358322	M37	80007354	2406204	1951	H
X39735	2320	008358322	M37	80007368	2406510	1951	H
X39735	2320	008358322	M37	80007643	2407645	1951	H
X39735	2320	008358322	M37	80007647	2407364	1951	C
X39735	2320	008358322	M37	80007663	2407363	1951	C
X39735	2320	008358322	M37	80007672	2407483	1951	H
X39735	2320	008358322	M37	80007683	2407412	1951	H
X39735	2320	008358322	M37	80007738	2407655	1951	C
X39735	2320	008358322	M37	80007936	2407592	1951	C
X39735	2320	008358322	M37	80007979	2407559	1951	C
X39735	2320	008358322	M37	80008025	2407583	1951	H
X39735	2320	008358322	M37	80008072	2371644	1951	H
X39735	2320	008358322	M37	80008146	2383375	1951	C
X39735	2320	008358322	M37	80008205	2406589	1951	C
X39735	2320	008358322	M37	80008266	3Z42551	1951	C
X39735	2320	008358322	M37	80008555	2383181	1951	H
X39735	2320	008358322	M37	80008638	2383165	1951	C
X39735	2320	008358322	M37	80008661	2383335	1951	C
X39735	2320	008358322	M37	80008694	2383328	1951	C
X39735	2320	008358322	M37	80008732	2383364	1951	C
X39735	2320	008358322	M37	80008738	2383355	1951	H
X39735	2320	008358322	M37	80008744	2383295	1951	H
X39735	2320	008358322	M37	80008765	2407598	1951	H
X39735	2320	008358322	M37	80008816	2406542	1951	C
X39735	2320	008358322	M37	80008856	2406524	1951	C
X39735	2320	008358322	M37	80008871	2383370	1951	C
X39735	2320	008358322	M37	80008920	24D6569	1951	C
X39735	2320	008358322	M37	80008961	2384575	1951	H
X39735	2320	008358322	M37	80008991	2383417	1951	H
X39735	2320	008358322	M37	80009099	2372079	1951	C
X39735	2320	008358322	M37	80009224	2383611	1951	C
X39735	2320	008358322	M37	80009225	2383700	1951	H
X39735	2320	008358322	M37	80009303	2372177	1951	C
X39735	2320	008358322	M37	80009328	2383695	1951	C
X39735	2320	008358322	M37	80009331	2383652	1951	C
X39735	2320	008358322	M37	80009335	2383759	1951	H
X39735	2320	008358322	M37	80009572	2383859	1951	H
X39735	2320	008358322	M37	80009574	2383980	1952	H
X39735	2320	008358322	M37	80009653	2401281	1951	H
X39735	2320	008358322	M37	80009690	2383814	1951	H
X39735	2320	008358322	M37	80009713	2384125	1951	H
X39735	2320	008358322	M37	80009756	2384627	1951	H
X39735	2320	008358322	M37	80009840	2383996	1951	H
X39735	2320	008358322	M37	80009859	2401096	1951	C
X39735	2320	008358322	M37	80009878	2384513	1951	H

X39735	2320	008358322	M37	80010073	2371265	1951	C
X39735	2320	008358322	M37	80010154	2384723	1951	H
X39735	2320	008358322	M37	80010183	2400996	1951	C
X39735	2320	008358322	M37	80010257	3C9873	1951	H
X39735	2320	008358322	M37	80010315	2384002	1951	C
X39735	2320	008358322	M37	80010386	2384022	1951	C
X39735	2320	008358322	M37	80010410	2384054	1951	H
X39735	2320	008358322	M37	80010419	2401816	1951	C
X39735	2320	008358322	M37	80010436	2384117	1951	C
X39735	2320	008358322	M37	80010451	2304066	1951	C
X39735	2320	008358322	M37	80010467	2384107	1951	C
X39735	2320	008358322	M37	80010524	2384114	1951	C
X39735	2320	008358322	M37	80010546	2384110	1951	H
X39735	2320	008358322	M37	80010760	3Z40251	1951	C
X39735	2320	008358322	M37	80010772	2384224	1951	H
X39735	2320	008358322	M37	80010783	2401112	1951	H
X39735	2320	008358322	M37	80010792	2384223	1951	C
X39735	2320	008358322	M37	80010903	2384273	1951	H
X39735	2320	008358322	M37	80010909	2384226	1951	H
X39735	2320	008358322	M37	800109979	2384690	1951	C
X39735	2320	008358322	M37	80011009	2384734	1951	C
X39735	2320	008358322	M37	80011015	2384378	1951	H
X39735	2320	008358322	M37	80011050	2384724	1951	C
X39735	2320	008358322	M37	80011052	2384716	1951	H
X39735	2320	008358322	M37	80011070	2384863	1951	H
X39735	2320	008358322	M37	800111115	2384861	1951	C
X39735	2320	008358322	M37	80011487	2384862	1951	C
X39735	2320	008358322	M37	80011566	2401335	1951	C
X39735	2320	008358322	M37	80011567	2401165	1951	C
X39735	2320	008358322	M37	80011568	2401110	1951	C
X39735	2320	008358322	M37	80011573	2401500	1951	C
X39735	2320	008358322	M37	80011598	2384894	1951	H
X39735	2320	008358322	M37	80011606	2384879	1951	C
X39735	2320	008358322	M37	80011607	2401227	1951	H
X39735	2320	008358322	M37	80011689	2384916	1951	H
X39735	2320	008358322	M37	80011788	2401298	1951	H
X39735	2320	008358322	M37	80011797	2401517	1951	H
X39735	2320	008358322	M37	80011849	2401565	1951	H
X39735	2320	008358322	M37	8001185	2401369	1951	C
X39735	2320	008358322	M37	80012053	2409121	1952	C
X39735	2320	008358322	M37	80012143	2401531	1951	H
X39735	2320	008358322	M37	80012164	2401563	1951	C
X39735	2320	008358322	M37	80012173	2401557	1951	C
X39735	2320	008358322	M37	80012185	2401622	1952	C
X39735	2320	008358322	M37	80012201	2401603	1951	H
X39735	2320	008358322	M37	80012245	2401810	1951	C
X39735	2320	008358322	M37	80012246	2401613	1951	C
X39735	2320	008358322	M37	800122469	2401790	1951	C
X39735	2320	008358322	M37	80012247	2401623	1951	H
X39735	2320	008358322	M37	80012461	2401874	1951	H
X39735	2320	008358322	M37	80012477	2401912	1951	H
X39735	2320	008358322	M37	8001251	2401577	1951	C

X39735	2320	008358322	M37	80012547	2401905	1951	H
X39735	2320	008358322	M37	80012797	2410301	1951	H
X39735	2320	008358322	M37	800131311	2422851	1952	H
X39735	2320	008358322	M37	80013180	2402446	1951	C
X39735	2320	008358322	M37	80013193	2402369	1966	H
X39735	2320	008358322	M37	80013347	2402378	1951	H
X39735	2320	008358322	M37	80013366	2402328	1951	H
X39735	2320	008358322	M37	80013402	2403469	1951	C
X39735	2320	008358322	M37	80013406	2402549	1951	H
X39735	2320	008358322	M37	80013605	2402789	1951	H
X39735	2320	008358322	M37	80013606		1951	H
X39735	2320	008358322	M37	80013715	2402649	1951	H
X39735	2320	008358322	M37	80013818	2402721	1951	C
X39735	2320	008358322	M37	80013942	2402768	1951	C
X39735	2320	008358322	M37	80013966	2402782	1951	H
X39735	2320	008358322	M37	80014098	2402814	1951	H
X39735	2320	008358322	M37	8001413	2430752	1952	H
X39735	2320	008358322	M37	8001428	2404616	1951	C
X39735	2320	008358322	M37	80014295	2409577	1951	C
X39735	2320	008358322	M37	8001493	2384820	1952	C
X39735	2320	008358322	M37	80015531	2411108	1951	H
X39735	2320	008358322	M37	80015611	2404023	1951	H
X39735	2320	008358322	M37	80015716	2404045	1951	C
X39735	2320	008358322	M37	80016171	2404581	1951	C
X39735	2320	008358322	M37	80016263	2404003	1951	C
X39735	2320	008358322	M37	80016264	2404009	1951	H
X39735	2320	008358322	M37	80016266	2403998	1951	C
X39735	2320	008358322	M37	80016325	2404637	1951	C
X39735	2320	008358322	M37	80016372	2404607	1951	C
X39735	2320	008358322	M37	80016395	2409684	1951	C
X39735	2320	008358322	M37	80016647	2409334	1951	H
X39735	2320	008358322	M37	80016749	2404715	1951	C
X39735	2320	008358322	M37	80016822	2404741	1951	C
X39735	2320	008358322	M37	80016844	2404674	1951	C
X39735	2320	008358322	M37	80016894	2404706	1951	H
X39735	2320	008358322	M37	80016968	2404652	1951	C
X39735	2320	008358322	M37	80017006	2433773	1951	C
X39735	2320	008358322	M37	80017014	2404773	1951	H
X39735	2320	008358322	M37	80017087	2404777	1951	C
X39735	2320	008358322	M37	80017128	2409152	1951	C
X39735	2320	008358322	M37	80017173	2409637	1951	C
X39735	2320	008358322	M37	80017201	2409343	1951	H
X39735	2320	008358322	M37	80017240	2404787	1951	C
X39735	2320	008358322	M37	80017254	2404816	1951	C
X39735	2320	008358322	M37	80017264	2409172	1951	H
X39735	2320	008358322	M37	80017391	2430784	1951	H
X39735	2320	008358322	M37	80017461	2410938	1951	H
X39735	2320	008358322	M37	80017498	3C9871	1951	C
X39735	2320	008358322	M37	8001751	2410709	1952	C
X39735	2320	008358322	M37	80017543	2410266	1951	H
X39735	2320	008358322	M37	80017581	2410122	1952	H
X39735	2320	008358322	M37	80017592	2409441	1951	H

X39735	2320	008358322	M37	80017604	2409696	1951	H
X39735	2320	008358322	M37	80017606	2409417	1951	H
X39735	2320	008358322	M37	80017672	2409521	1951	C
X39735	2320	008358322	M37	80017695	2409423	1951	C
X39735	2320	008358322	M37	80017795		1951	H
X39735	2320	008358322	M37	80017844	2409888	1951	C
X39735	2320	008358322	M37	80017851	2409554	1951	C
X39735	2320	008358322	M37	80017907	2409788	1951	H
X39735	2320	008358322	M37	80017949	2409617	1952	H
X39735	2320	008358322	M37	8001799	2404791	1951	H
X39735	2320	008358322	M37	80018007	2409765	1952	H
X39735	2320	008358322	M37	800181413	2410611	1952	C
X39735	2320	008358322	M37	80018153	2409966	1952	H
X39735	2320	008358322	M37	80018235	2409878	1952	H
X39735	2320	008358322	M37	800183000	2410105	1952	H
X39735	2320	008358322	M37	80018328	2409911	1952	H
X39735	2320	008358322	M37	80018395	2410051	1952	H
X39735	2320	008358322	M37	80018406	2410400	1952	C
X39735	2320	008358322	M37	80018431	2410022	1955	H
X39735	2320	008358322	M37	80018445	2410014	1952	H
X39735	2320	008358322	M37	80018458	2409992	1952	H
X39735	2320	008358322	M37	80018534	2410150	1952	H
X39735	2320	008358322	M37	80018592	2411398	1952	C
X39735	2320	008358322	M37	80018622	2410403	1952	C
X39735	2320	008358322	M37	80018673	2410432	1952	H
X39735	2320	008358322	M37	80018704	2410213	1952	C
X39735	2320	008358322	M37	80018710	6F1454	1952	C
X39735	2320	008358322	M37	80018760	2410300	1952	H
X39735	2320	008358322	M37	80018772	2410285	1968	C
X39735	2320	008358322	M37	80019071	2410509	1952	C
X39735	2320	008358322	M37	80019168	2410649	1952	C
X39735	2320	008358322	M37	80019274	2410567	1952	C
X39735	2320	008358322	M37	80019299	2410654	1952	C
X39735	2320	008358322	M37	80019318	2411369	1952	H
X39735	2320	008358322	M37	80019385	2430807	1952	H
X39735	2320	008358322	M37	80019440	2430687	1952	H
X39735	2320	008358322	M37	80019474	2410964	1952	C
X39735	2320	008358322	M37	800195	2410984	1952	C
X39735	2320	008358322	M37	80019674	2410963	1952	H
X39735	2320	008358322	M37	80019767	2411388	1952	H
X39735	2320	008358322	M37	8001978	1008166	1952	C
X39735	2320	008358322	M37	80019926	2411174	1952	H
X39735	2320	008358322	M37	80019936	2411185	1952	C
X39735	2320	008358322	M37	80019945	2411001	1952	H
X39735	2320	008358322	M37	80019977	2410992	1952	H
X39735	2320	008358322	M37	80020010	2410987	1952	C
X39735	2320	008358322	M37	800200499	2408499	1952	C
X39735	2320	008358322	M37	80020252	2411227	1952	C
X39735	2320	008358322	M37	80020285	2411307	1952	C
X39735	2320	008358322	M37	80020424	2411314	1952	C
X39735	2320	008358322	M37	80020428	2411338	1952	H
X39735	2320	008358322	M37	80020508	2402263	1952	H

X39735	2320	008358322	M37	80020604	2411375	1952	H
X39735	2320	008358322	M37	80020706	2411561	1952	H
X39735	2320	008358322	M37	80020819	2411760	1952	H
X39735	2320	008358322	M37	80020847	2411747	1952	C
X39735	2320	008358322	M37	80020860	2412096	1952	H
X39735	2320	008358322	M37	80020863	2410410	1952	H
X39735	2320	008358322	M37	80021014	2411746	1952	C
X39735	2320	008358322	M37	80021017	2411750	1952	C
X39735	2320	008358322	M37	80021159	2430660	1952	H
X39735	2320	008358322	M37	80021201	2412326	1952	C
X39735	2320	008358322	M37	80021326	2408479	1952	H
X39735	2320	008358322	M37	80021355	2412167	1952	H
X39735	2320	008358322	M37	80021405	2422108	1952	H
X39735	2320	008358322	M37	80021419	2411990	1952	C
X39735	2320	008358322	M37	8002146	2412052	1952	C
X39735	2320	008358322	M37	80021649	2412530	1952	H
X39735	2320	008358322	M37	80021702	2412284	1952	H
X39735	2320	008358322	M37	80021777	2412490	1952	H
X39735	2320	008358322	M37	80021783	2413014	1952	H
X39735	2320	008358322	M37	80021807	2412403	1952	C
X39735	2320	008358322	M37	80021987	2412561	1952	C
X39735	2320	008358322	M37	80021995	2423257	1952	H
X39735	2320	008358322	M37	80022261	2430624	1952	C
X39735	2320	008358322	M37	80022369	2412695	1952	H
X39735	2320	008358322	M37	80022459	2405383	1952	C
X39735	2320	008358322	M37	80022466	2413156	1952	C
X39735	2320	008358322	M37	80022641	2408710	1952	H
X39735	2320	008358322	M37	80022796	2412881	1952	H
X39735	2320	008358322	M37	80022841	2402980	1952	C
X39735	2320	008358322	M37	80022885	2412885	1952	C
X39735	2320	008358322	M37	80022977	2430718	1952	C
X39735	2320	008358322	M37	80023003	2421074	1952	H
X39735	2320	008358322	M37	80023091	2430823	1952	C
X39735	2320	008358322	M37	80023269	2430574	1952	H
X39735	2320	008358322	M37	80023286	2408767	1952	C
X39735	2320	008358322	M37	80023295	2430577	1952	C
X39735	2320	008358322	M37	80023355	2408750	1952	C
X39735	2320	008358322	M37	80023461	2430710	1952	H
X39735	2320	008358322	M37	80023511	2430617	1952	C
X39735	2320	008358322	M37	80023575	2430583	1952	H
X39735	2320	008358322	M37	80023587	2430686	1952	C
X39735	2320	008358322	M37	80023633	2430579	1952	C
X39735	2320	008358322	M37	80023646	2430754	1952	H
X39735	2320	008358322	M37	80023687	2430735	1952	H
X39735	2320	008358322	M37	80023733	2430580	1952	H
X39735	2320	008358322	M37	80023746	2420523	1952	H
X39735	2320	008358322	M37	80023795	2430614	1952	H
X39735	2320	008358322	M37	80024181	2427154	1952	H
X39735	2320	008358322	M37	80024333	3C9611	1952	C
X39735	2320	008358322	M37	80024356	3A6671	1952	C
X39735	2320	008358322	M37	80024440	3C9916	1952	C
X39735	2320	008358322	M37	80024500	3C9635	1952	H



X39735	2320	008358322	M37	80024694	3B3112	1952	H
X39735	2320	008358322	M37	80024717	3B2982	1952	C
X39735	2320	008358322	M37	80024786	2430811	1952	H
X39735	2320	008358322	M37	80024838	3B2159	1952	H
X39735	2320	008358322	M37	80024911	3B3207	1952	C
X39735	2320	008358322	M37	80025146	3B2264	1952	H
X39735	2320	008358322	M37	80025343	3G2608	1952	H
X39735	2320	008358322	M37	80025397	3B3258	1952	H
X39735	2320	008358322	M37	80025425	3B2412	1952	C
X39735	2320	008358322	M37	80025526	3A4312	1952	C
X39735	2320	008358322	M37	80025574	3A0566	1952	C
X39735	2320	008358322	M37	80025587	20100954	1952	H
X39735	2320	008358322	M37	80025904	3F0513	1952	C
X39735	2320	008358322	M37	80025964	3B2388	1952	C
X39735	2320	008358322	M37	8002599	3B3250	1952	H
X39735	2320	008358322	M37	80026135	3B2471	1952	H
X39735	2320	008358322	M37	8002615	3B2365	1952	C
X39735	2320	008358322	M37	800261658	2442295	1954	C
X39735	2320	008358322	M37	80026254	2442920	1954	C
X39735	2320	008358322	M37	80026275	2423658	1952	H
X39735	2320	008358322	M37	80026487	3B2974	1952	C
X39735	2320	008358322	M37	80026529	3B2399	1952	H
X39735	2320	008358322	M37	80026869	3B2173	1952	C
X39735	2320	008358322	M37	80026899	3B3300	1952	H
X39735	2320	008358322	M37	80027029	3C4022	1952	H
X39735	2320	008358322	M37	80027335	2420528	1952	H
X39735	2320	008358322	M37	80027354	2406494	1952	H
X39735	2320	008358322	M37	80027387	2420538	1952	H
X39735	2320	008358322	M37	80027395	2420779	1952	H
X39735	2320	008358322	M37	80027422	2420759	1972	C
X39735	2320	008358322	M37	80027431	2420561	1952	H
X39735	2320	008358322	M37	80027456	2420853	1952	H
X39735	2320	008358322	M37	80027478	2420829	1952	C
X39735	2320	008358322	M37	80027493	2420637	1952	H
X39735	2320	008358322	M37	80027521	2420608	1952	C
X39735	2320	008358322	M37	80027556	2420609	1952	C
X39735	2320	008358322	M37	80027608	2420580	1952	H
X39735	2320	008358322	M37	80027651	2427550	1951	H
X39735	2320	008358322	M37	80027690	2420638	1952	H
X39735	2320	008358322	M37	80027746	2420662	1952	H
X39735	2320	008358322	M37	80027818	2420690	1952	C
X39735	2320	008358322	M37	80027828	2420696	1952	H
X39735	2320	008358322	M37	80027832	2420901	1952	C
X39735	2320	008358322	M37	80027894	2420859	1952	H
X39735	2320	008358322	M37	80027901	2421032	1952	H
X39735	2320	008358322	M37	80027909	2420852	1952	C
X39735	2320	008358322	M37	80027933	2420813	1952	C
X39735	2320	008358322	M37	80027949	3Z40352	1952	C
X39735	2320	008358322	M37	80027983	2420800	1952	H
X39735	2320	008358322	M37	80028083	2420860	1952	C
X39735	2320	008358322	M37	80028137	2420890	1952	C
X39735	2320	008358322	M37	80028162	2420936	1952	H

X39735	2320	008358322	M37	80028174	2427386	1952	H
X39735	2320	008358322	M37	80028181	2420929	1952	C
X39735	2320	008358322	M37	80028203	2420955	1952	C
X39735	2320	008358322	M37	80028209	2420915	1952	C
X39735	2320	008358322	M37	80028237	2420868	1952	C
X39735	2320	008358322	M37	80028246	2420976	1952	H
X39735	2320	008358322	M37	80028248	2420943	1952	H
X39735	2320	008358322	M37	80028265	2420966	1952	H
X39735	2320	008358322	M37	80028271	2421017	1952	C
X39735	2320	008358322	M37	80028278	2420950	1952	C
X39735	2320	008358322	M37	80028297	2421092	1952	H
X39735	2320	008358322	M37	80028300	2420964	1952	H
X39735	2320	008358322	M37	80028310	2421004	1952	C
X39735	2320	008358322	M37	80028334	2427432	1962	H
X39735	2320	008358322	M37	8002835	2421040	1952	H
X39735	2320	008358322	M37	80028493	2421088	1952	H
X39735	2320	008358322	M37	80028513	2421073	1952	C
X39735	2320	008358322	M37	80028638	2421234	1952	H
X39735	2320	008358322	M37	80028766	2423203	1952	C
X39735	2320	008358322	M37	80028878	2420834	1952	C
X39735	2320	008358322	M37	80028925	2427571	1952	C
X39735	2320	008358322	M37	80028939	2427558	1952	C
X39735	2320	008358322	M37	80029010	2421383	1952	H
X39735	2320	008358322	M37	80029099	2421401	1952	H
X39735	2320	008358322	M37	80029172	2421453	1952	C
X39735	2320	008358322	M37	80029195	2441521	1952	H
X39735	2320	008358322	M37	80029209	2427597	1952	C
X39735	2320	008358322	M37	80029303	2423080	1952	H
X39735	2320	008358322	M37	80029560	2423168	1952	H
X39735	2320	008358322	M37	80029609	2423161	1952	C
X39735	2320	008358322	M37	8002998	2427853	1952	H
X39735	2320	008358322	M37	80030054	2423141	1952	C
X39735	2320	008358322	M37	80030061	2423247	1952	H
X39735	2320	008358322	M37	80030067	2423230	1952	H
X39735	2320	008358322	M37	80030614	2423187	1952	H
X39735	2320	008358322	M37	80030855	2422360	1952	H
X39735	2320	008358322	M37	8003099	2422084	1952	H
X39735	2320	008358322	M37	80031138	2422949	1952	H
X39735	2320	008358322	M37	80031217	2422991	1952	H
X39735	2320	008358322	M37	80031306	2423119	1952	C
X39735	2320	008358322	M37	80031363	2422960	1952	C
X39735	2320	008358322	M37	80031378	2422707	1952	C
X39735	2320	008358322	M37	80031379	2423210	1952	H
X39735	2320	008358322	M37	80031384	2422731	1952	H
X39735	2320	008358322	M37	80031419	2423234	1952	H
X39735	2320	008358322	M37	80031456	2423177	1952	C
X39735	2320	008358322	M37	80031532	2423160	1952	C
X39735	2320	008358322	M37	80031542	2422843	1952	H
X39735	2320	008358322	M37	80031552	2422739	1952	H
X39735	2320	008358322	M37	80031605	2423004	1952	H
X39735	2320	008358322	M37	80031741	2422938	1952	H
X39735	2320	008358322	M37	80031760	3Z42652	1952	C

X39735	2320	008358322	M37	80031840	2423011	1952	H
X39735	2320	008358322	M37	80031966	2405479	1952	C
X39735	2320	008358322	M37	80032018	2405241	1952	H
X39735	2320	008358322	M37	80032023	2405170	1952	C
X39735	2320	008358322	M37	80032088	2405203	1955	H
X39735	2320	008358322	M37	80032122	2405294	1952	H
X39735	2320	008358322	M37	80032161	2405229	1952	H
X39735	2320	008358322	M37	80032171	2405312	1952	H
X39735	2320	008358322	M37	8003218	2405470	1952	H
X39735	2320	008358322	M37	80032262	2405268	1952	C
X39735	2320	008358322	M37	80032336	20940872	1952	H
X39735	2320	008358322	M37	80032357	2405337	1959	C
X39735	2320	008358322	M37	80032376	2405392	1952	C
X39735	2320	008358322	M37	80032382	2405431	1962	H
X39735	2320	008358322	M37	80032434	2405360	1952	C
X39735	2320	008358322	M37	80032528	2405413	1952	H
X39735	2320	008358322	M37	80032543	2405419	1952	H
X39735	2320	008358322	M37	80032548	2405553	1952	H
X39735	2320	008358322	M37	80032553	2405496	1953	C
X39735	2320	008358322	M37	80032591	2405505	1952	H
X39735	2320	008358322	M37	80032610	20939241	1951	H
X39735	2320	008358322	M37	80032647	2405498	1969	H
X39735	2320	008358322	M37	80032653	2405565	1952	H
X39735	2320	008358322	M37	80032741	2405551	1952	C
X39735	2320	008358322	M37	80032847	20939998	1952	H
X39735	2320	008358322	M37	80032942	20940062	1952	H
X39735	2320	008358322	M37	80033141		1952	C
X39735	2320	008358322	M37	8003316	20940065	1952	H
X39735	2320	008358322	M37	80033871	20940583	1952	H
X39735	2320	008358322	M37	80033872	20940865	1952	H
X39735	2320	008358322	M37	80034351	20941221	1952	C
X39735	2320	008358322	M37	8003436	20954775	1952	H
X39735	2320	008358322	M37	80034407	20941133	1952	C
X39735	2320	008358322	M37	80034527	20941315	1952	C
X39735	2320	008358322	M37	80034566	20941210	1952	C
X39735	2320	008358322	M37	80034582	20954958	1952	H
X39735	2320	008358322	M37	80034611	20954836	1952	H
X39735	2320	008358322	M37	8003467	2094353	1952	C
X39735	2320	008358322	M37	80034698	20941284	1952	H
X39735	2320	008358322	M37	80034908	2423422	1952	H
X39735	2320	008358322	M37	80035052	2405233	1952	C
X39735	2320	008358322	M37	80035306	20954841	1952	H
X39735	2320	008358322	M37	80035909	2428137	1952	C
X39735	2320	008358322	M37	80036081	3B2401	1952	H
X39735	2320	008358322	M37	80036831	2400496	1952	H
X39735	2320	008358322	M37	80037428	2426400	1952	H
X39735	2320	008358322	M37	80037476	2425002	1952	C
X39735	2320	008358322	M37	80037688	2424311	1952	H
X39735	2320	008358322	M37	80038073	2426251	1952	H
X39735	2320	008358322	M37	80038414	2425625	1952	H
X39735	2320	008358322	M37	8003843	2432213	1952	H
X39735	2320	008358322	M37	80038615	20955313	1952	H

X39735	2320	008358322	M37	80039043	2426182	1952	H
X39735	2320	008358322	M37	80039152	2426158	1957	C
X39735	2320	008358322	M37	80039210	2426194	1952	H
X39735	2320	008358322	M37	80039219	2426286	1952	H
X39735	2320	008358322	M37	80039305	2426396	1953	H
X39735	2320	008358322	M37	80039320	2426221	1952	H
X39735	2320	008358322	M37	80039349	2426331	1952	H
X39735	2320	008358322	M37	80039492	2426414	1952	C
X39735	2320	008358322	M37	80039527	2426386	1952	C
X39735	2320	008358322	M37	80039544	2426380	1952	C
X39735	2320	008358322	M37	80039582	2426385	1952	H
X39735	2320	008358322	M37	80039637	20955102	1952	C
X39735	2320	008358322	M37	80039653	2426372	1952	H
X39735	2320	008358322	M37	80039745	20955393	1952	C
X39735	2320	008358322	M37	80039802	20955064	1952	C
X39735	2320	008358322	M37	80039840	2095593	1952	H
X39735	2320	008358322	M37	80039844	20955093	1952	H
X39735	2320	008358322	M37	80039863	20955766	1952	C
X39735	2320	008358322	M37	80039994	20955399	1952	H
X39735	2320	008358322	M37	8003L342	24D5342	1952	H
X39735	2320	008358322	M37	80040032	2429214	1952	C
X39735	2320	008358322	M37	80040084	20955317	1952	C
X39735	2320	008358322	M37	80040142	2434312	1952	H
X39735	2320	008358322	M37	80040162	20955218	1952	H
X39735	2320	008358322	M37	80040176	20955299	1952	H
X39735	2320	008358322	M37	80040197	20955502	1952	H
X39735	2320	008358322	M37	80040268	21007932	1952	H
X39735	2320	008358322	M37	80040323	3Z42752	1952	C
X39735	2320	008358322	M37	80040366	20955615	1952	C
X39735	2320	008358322	M37	80040426	20955315	1952	C
X39735	2320	008358322	M37	80040441	20955454	1952	H
X39735	2320	008358322	M37	80040487	20955458	1952	C
X39735	2320	008358322	M37	80040500	20955542	1952	C
X39735	2320	008358322	M37	80040510	20955672	1952	H
X39735	2320	008358322	M37	80040519	20955523	1952	C
X39735	2320	008358322	M37	80040527	20955576	1952	C
X39735	2320	008358322	M37	80040533	20955452	1952	C
X39735	2320	008358322	M37	80040593	20955462	1952	C
X39735	2320	008358322	M37	80040616	20955440	1952	C
X39735	2320	008358322	M37	80040623	20955464	1952	C
X39735	2320	008358322	M37	80040637	20955616	1952	C
X39735	2320	008358322	M37	80040643H3	20955546	1952	H
X39735	2320	008358322	M37	80040648	20955446	1952	C
X39735	2320	008358322	M37	80040651	2410147	1952	H
X39735	2320	008358322	M37	80040653	20955626	1952	C
X39735	2320	008358322	M37	80040686	20955805	1952	C
X39735	2320	008358322	M37	80040692	20955617	1952	C
X39735	2320	008358322	M37	80040711	20955557	1952	H
X39735	2320	008358322	M37	80040712	20955503	1952	C
X39735	2320	008358322	M37	80040741	20955567	1952	H
X39735	2320	008358322	M37	80040782	2095543	1952	H
X39735	2320	008358322	M37	80040825	20955563	1952	C

X39735	2320	008358322	M37	80040826	20955813	1952	H
X39735	2320	008358322	M37	80040838	20955744	1952	C
X39735	2320	008358322	M37	80040875	20955784	1952	C
X39735	2320	008358322	M37	80040877	20955752	1952	C
X39735	2320	008358322	M37	8004090	2410069	1952	C
X39735	2320	008358322	M37	80040915	20955628	1952	H
X39735	2320	008358322	M37	80040920	20955706	1952	H
X39735	2320	008358322	M37	80040931	20955776	1952	C
X39735	2320	008358322	M37	80040932	20955723	1952	C
X39735	2320	008358322	M37	80040948	20955815	1952	H
X39735	2320	008358322	M37	80040956	20955700	1952	C
X39735	2320	008358322	M37	80040958	20955712	1952	H
X39735	2320	008358322	M37	80041018	2426493	1952	C
X39735	2320	008358322	M37	80041036	2426545	1952	H
X39735	2320	008358322	M37	80041104	2426535	1952	C
X39735	2320	008358322	M37	80041164	2427048	1952	C
X39735	2320	008358322	M37	80041220	2426555	1952	H
X39735	2320	008358322	M37	80041279	2426643	1952	H
X39735	2320	008358322	M37	80041280	2426573	1952	C
X39735	2320	008358322	M37	80041576	2431913	1952	H
X39735	2320	008358322	M37	80041725	2426859	1952	C
X39735	2320	008358322	M37	80041776	2427010	1952	H
X39735	2320	008358322	M37	80041838	2433887	1952	H
X39735	2320	008358322	M37	80041863	2426979	1952	C
X39735	2320	008358322	M37	80042050	2427093	1952	C
X39735	2320	008358322	M37	80042092	2427218	1952	H
X39735	2320	008358322	M37	80042115	20956288	1952	H
X39735	2320	008358322	M37	80042155	2427197	1952	C
X39735	2320	008358322	M37	80042266	2431316	1952	H
X39735	2320	008358322	M37	80042296	20956308	1952	H
X39735	2320	008358322	M37	80042320	2427259	1952	C
X39735	2320	008358322	M37	80042417	2431341	1952	C
X39735	2320	008358322	M37	80042485	3J24313	1952	H
X39735	2320	008358322	M37	80042572	2429263	1972	H
X39735	2320	008358322	M37	80042654	2431591	1952	C
X39735	2320	008358322	M37	80043125	2431793	1952	H
X39735	2320	008358322	M37	80043212	2431700	1953	C
X39735	2320	008358322	M37	80043413	2431298	1952	C
X39735	2320	008358322	M37	800435594	2432471	1952	C
X39735	2320	008358322	M37	80043691	2434182	1952	H
X39735	2320	008358322	M37	80043797	2432726	1952	H
X39735	2320	008358322	M37	80043872	3C4017	1953	H
X39735	2320	008358322	M37	80043995	2434065	1953	H
X39735	2320	008358322	M37	80044294	3B2828	1953	C
X39735	2320	008358322	M37	80044384	3B2740	1953	H
X39735	2320	008358322	M37	80044772	2432012	1952	H
X39735	2320	008358322	M37	800447741	2434402	1953	C
X39735	2320	008358322	M37	800449151	2434368	1953	C
X39735	2320	008358322	M37	80045139	2432630	1953	C
X39735	2320	008358322	M37	80045274	1007955	1953	H
X39735	2320	008358322	M37	80045464	2410394	1953	H
X39735	2320	008358322	M37	80045466	20955923	1953	C

X39735	2320	008358322	M37	80045518	1007827	1953	H
X39735	2320	008358322	M37	80045535	1007930	1953	H
X39735	2320	008358322	M37	80045543	2095539	1953	H
X39735	2320	008358322	M37	80045628	20955965	1953	H
X39735	2320	008358322	M37	80045693	20955962	1953	H
X39735	2320	008358322	M37	80045728	1007959	1953	H
X39735	2320	008358322	M37	80045742	1067852	1953	C
X39735	2320	008358322	M37	80045754	20955946	1953	C
X39735	2320	008358322	M37	80045788	1007901	1953	H
X39735	2320	008358322	M37	80045819	20100788	1953	C
X39735	2320	008358322	M37	80045899	1007812	1953	H
X39735	2320	008358322	M37	80045939	1007877	1953	H
X39735	2320	008358322	M37	80045960	1007914	1953	H
X39735	2320	008358322	M37	80045995	1007990	1953	H
X39735	2320	008358322	M37	80045999	1007913	1953	C
X39735	2320	008358322	M37	8004601	20955801	1952	C
X39735	2320	008358322	M37	8004630	2433630	1952	C
X39735	2320	008358322	M37	80046600	2433215	1953	H
X39735	2320	008358322	M37	80046723	2433506	1953	H
X39735	2320	008358322	M37	80046887	2433175	1952	C
X39735	2320	008358322	M37	80046951	2425516	1953	H
X39735	2320	008358322	M37	80046968	2434259	1953	C
X39735	2320	008358322	M37	80046983	2433282	1953	H
X39735	2320	008358322	M37	80047004	2434309	1953	H
X39735	2320	008358322	M37	80047014	2433514	1953	C
X39735	2320	008358322	M37	80047031	2423687	1953	C
X39735	2320	008358322	M37	80047051	2433271	1953	H
X39735	2320	008358322	M37	80047077	2433433	1953	H
X39735	2320	008358322	M37	80047137	2433435	1953	C
X39735	2320	008358322	M37	80047195	2433551	1953	C
X39735	2320	008358322	M37	80047273	2433511	1953	C
X39735	2320	008358322	M37	80047274	2434243	1953	H
X39735	2320	008358322	M37	80047297	2433869	1953	C
X39735	2320	008358322	M37	80047308	2433390	1953	H
X39735	2320	008358322	M37	80047368	2433618	1953	H
X39735	2320	008358322	M37	80047404	2433446	1953	C
X39735	2320	008358322	M37	80047413	2433458	1953	C
X39735	2320	008358322	M37	80047453	2433779	1953	C
X39735	2320	008358322	M37	80047465	2433537	1953	H
X39735	2320	008358322	M37	80047512	2434501	1953	C
X39735	2320	008358322	M37	80047547	2433742	1953	C
X39735	2320	008358322	M37	80047550	2433470	1953	C
X39735	2320	008358322	M37	80047572	2433548	1953	C
X39735	2320	008358322	M37	80047574	2433499	1953	H
X39735	2320	008358322	M37	80047641	2433650	1953	H
X39735	2320	008358322	M37	80047662	2433684	1953	H
X39735	2320	008358322	M37	80047684	2433617	1953	C
X39735	2320	008358322	M37	80047728	2433899	1953	C
X39735	2320	008358322	M37	80047730	2433675	1953	H
X39735	2320	008358322	M37	80047731	2433626	1953	H
X39735	2320	008358322	M37	80047752	2433642	1953	C
X39735	2320	008358322	M37	80047756	2433807	1953	H

X39735	2320	008358322	M37	80047796	2433695	1953	C
X39735	2320	008358322	M37	80047929	2433803	1953	H
X39735	2320	008358322	M37	80047952	2433854	1953	C
X39735	2320	008358322	M37	80047966	2433814	1953	C
X39735	2320	008358322	M37	80047976	2433978	1953	C
X39735	2320	008358322	M37	80048006	2433872	1953	C
X39735	2320	008358322	M37	80048009	2434001	1953	C
X39735	2320	008358322	M37	80048041	2433883	1953	C
X39735	2320	008358322	M37	80048051	2434016	1953	C
X39735	2320	008358322	M37	80048054	2433876	1953	H
X39735	2320	008358322	M37	80048060	2433916	1953	C
X39735	2320	008358322	M37	80048140	2433908	1953	C
X39735	2320	008358322	M37	8004815	2433877	1952	H
X39735	2320	008358322	M37	80048187	2433996	1953	H
X39735	2320	008358322	M37	80048219	2434292	1953	C
X39735	2320	008358322	M37	80048266	2433949	1953	C
X39735	2320	008358322	M37	80048268	2433998	1952	H
X39735	2320	008358322	M37	80048269	2433989	1953	C
X39735	2320	008358322	M37	80048312	2434033	1953	C
X39735	2320	008358322	M37	80048326	2434116	1953	C
X39735	2320	008358322	M37	80048335	2433976	1953	H
X39735	2320	008358322	M37	80048394	2434062	1953	C
X39735	2320	008358322	M37	80048422	3C9774	1953	H
X39735	2320	008358322	M37	80048528	3A4235	1953	H
X39735	2320	008358322	M37	80048560	2434163	1953	C
X39735	2320	008358322	M37	80048566	2434103	1953	H
X39735	2320	008358322	M37	80048588	2434267	1953	C
X39735	2320	008358322	M37	80048654	3E3091	1953	C
X39735	2320	008358322	M37	80048673	2434185	1953	C
X39735	2320	008358322	M37	80048732	2434169	1953	C
X39735	2320	008358322	M37	80048748	2434463	1953	C
X39735	2320	008358322	M37	80048751	20955565	1953	H
X39735	2320	008358322	M37	80048757	2434500	1953	C
X39735	2320	008358322	M37	80048770	2434216	1953	C
X39735	2320	008358322	M37	80048790	2434188	1953	C
X39735	2320	008358322	M37	80048813	2434239	1953	C
X39735	2320	008358322	M37	80048824	2434238	1953	H
X39735	2320	008358322	M37	80048830	2434220	1953	C
X39735	2320	008358322	M37	80048851		1953	C
X39735	2320	008358322	M37	80048856	2434286	1956	C
X39735	2320	008358322	M37	80048871	2434461	1953	H
X39735	2320	008358322	M37	80048877	2434257	1953	C
X39735	2320	008358322	M37	80048920	2434348	1953	C
X39735	2320	008358322	M37	80049018	2434357	1953	C
X39735	2320	008358322	M37	80049099	3C9798	1953	H
X39735	2320	008358322	M37	80049120	3C4025	1953	C
X39735	2320	008358322	M37	80049191	2434365	1953	H
X39735	2320	008358322	M37	80049284	2434408	1953	C
X39735	2320	008358322	M37	80049289	2434363	1953	C
X39735	2320	008358322	M37	80049331	2434364	1953	C
X39735	2320	008358322	M37	80049346	2408731	1953	C
X39735	2320	008358322	M37	80049371	2434489	1953	C

X39735	2320	008358322	M37	80049391	2434440	1953	C
X39735	2320	008358322	M37	80049396	2434460	1953	C
X39735	2320	008358322	M37	80049402	2434446	1953	C
X39735	2320	008358322	M37	80049410	3B2590	1953	H
X39735	2320	008358322	M37	80049497	2434484	1953	H
X39735	2320	008358322	M37	80049499	2434468	1953	H
X39735	2320	008358322	M37	80049517	2434478	1953	C
X39735	2320	008358322	M37	80049552	2434448	1953	H
X39735	2320	008358322	M37	80049575	2434525	1953	C
X39735	2320	008358322	M37	80049583	2434496	1953	C
X39735	2320	008358322	M37	80049596	2434493	1953	C
X39735	2320	008358322	M37	80049598	2434508	1953	C
X39735	2320	008358322	M37	80049619	2434499	1953	C
X39735	2320	008358322	M37	80049672	2406865	1953	C
X39735	2320	008358322	M37	800498011	2434503	1953	C
X39735	2320	008358322	M37	80049828	1008130	1953	C
X39735	2320	008358322	M37	80049872	1008106	1953	H
X39735	2320	008358322	M37	80049880	20100809	1953	C
X39735	2320	008358322	M37	80049884	3B2663	1953	C
X39735	2320	008358322	M37	80050056	1008135	1953	H
X39735	2320	008358322	M37	80050101	2435847	1953	C
X39735	2320	008358322	M37	80050337	1008085	1953	H
X39735	2320	008358322	M37	80050495	1010170	1953	C
X39735	2320	008358322	M37	80050527	2421418	1953	C
X39735	2320	008358322	M37	80050559	3B2698	1953	C
X39735	2320	008358322	M37	80050619	3B2702	1953	C
X39735	2320	008358322	M37	80050641	3B2612	1953	H
X39735	2320	008358322	M37	80051101	3C9776	1953	H
X39735	2320	008358322	M37	80051264	20101029	1953	C
X39735	2320	008358322	M37	80051268	2437047	1953	H
X39735	2320	008358322	M37	80051403	3A8427	1953	H
X39735	2320	008358322	M37	80051464	3A8462	1953	C
X39735	2320	008358322	M37	80051764	20100813	1953	H
X39735	2320	008358322	M37	80051857	1008155	1953	H
X39735	2320	008358322	M37	80051884	2434879	1952	H
X39735	2320	008358322	M37	80051978	20100816	1953	C
X39735	2320	008358322	M37	80052030	1008153	1953	H
X39735	2320	008358322	M37	80052071	1008175	1953	C
X39735	2320	008358322	M37	80052118	3E2920	1953	C
X39735	2320	008358322	M37	80052350	3A8534	1953	C
X39735	2320	008358322	M37	80052359	3A8415	1953	C
X39735	2320	008358322	M37	80052371	3A8616	1953	C
X39735	2320	008358322	M37	80052593	2437396	1953	H
X39735	2320	008358322	M37	80052667	2437330	1953	C
X39735	2320	008358322	M37	80052813	3A8495	1953	H
X39735	2320	008358322	M37	80053146	1008237	1953	C
X39735	2320	008358322	M37	80053339	3E2924	1953	C
X39735	2320	008358322	M37	80054248	2437049	1953	H
X39735	2320	008358322	M37	80054411	3A8358	1953	H
X39735	2320	008358322	M37	80054464	2437218	1953	H
X39735	2320	008358322	M37	80054466	3B2829	1953	C
X39735	2320	008358322	M37	80054607	2437195	1953	H



X39735	2320	008358322	M37	80054698	20100832	1953	C
X39735	2320	008358322	M37	80054809	2438066	1953	C
X39735	2320	008358322	M37	80054817	2438125	1953	C
X39735	2320	008358322	M37	80054836	2438137	1953	C
X39735	2320	008358322	M37	80054843	1008318	1953	H
X39735	2320	008358322	M37	80054871	2437279	1953	C
X39735	2320	008358322	M37	80054926	1008324	1953	H
X39735	2320	008358322	M37	80054934	2437196	1953	C
X39735	2320	008358322	M37	80054958	2437544	1953	C
X39735	2320	008358322	M37	80058804	20100826	1953	C
X39735	2320	008358322	M37	8006115	2407065	1952	C
X39735	2320	008358322	M37	8006204	2371676	1951	C
X39735	2320	008358322	M37	8006365	2371790	1951	H
X39735	2320	008358322	M37	800640	2407111	1952	C
X39735	2320	008358322	M37	80067360	2406509	1953	C
X39735	2320	008358322	M37	8006792	2407105	1952	C
X39735	2320	008358322	M37	8006970	2406350	1952	H
X39735	2320	008358322	M37	8007236	2406389	1952	H
X39735	2320	008358322	M37	8007252	2406431	1952	C
X39735	2320	008358322	M37	80072918	2420828	1953	C
X39735	2320	008358322	M37	8007302	2406447	1952	C
X39735	2320	008358322	M37	80074948	2433772	1953	C
X39735	2320	008358322	M37	8007559	2407439	1952	H
X39735	2320	008358322	M37	8007592	2433517	1952	C
X39735	2320	008358322	M37	8007595	2407461	1952	H
X39735	2320	008358322	M37	8007603	2420791	1952	C
X39735	2320	008358322	M37	8007697	2407441	1952	C
X39735	2320	008358322	M37	8008591	2383074	1951	H
X39735	2320	008358322	M37	8008661	238335	1952	C
X39735	2320	008358322	M37	80098950	2372114	1953	C
X39735	2320	008358322	M37	80118755	240292	1953	C
X39735	2320	008358322	M37	8011944	2401421	1951	H
X39735	2320	008358322	M37	8019179	2410603	1953	H
X39735	2320	008358322	M37	802255843	1009775	1953	H
X39735	2320	008358322	M37	802257173	1010022	1953	H
X39735	2320	008358322	M37	80225909	20109699	1953	C
X39735	2320	008358322	M37	80232795	1008977	1953	H
X39735	2320	008358322	M37	80232835	2093995	1953	H
X39735	2320	008358322	M37	80243550	3B3129	1953	C
X39735	2320	008358322	M37	80250080	2437283	1953	C
X39735	2320	008358322	M37	80250095	1008332	1953	C
X39735	2320	008358322	M37	80250181	1008334	1953	H
X39735	2320	008358322	M37	80250200	1008942	1953	C
X39735	2320	008358322	M37	80250202	1008575	1953	H
X39735	2320	008358322	M37	80250339	1008347	1953	C
X39735	2320	008358322	M37	80250446	2438120	1953	H
X39735	2320	008358322	M37	80250448	1008369	1953	H
X39735	2320	008358322	M37	80250455	3A8733	1953	C
X39735	2320	008358322	M37	80250481	2438149	1953	C
X39735	2320	008358322	M37	80250490	1008395	1953	H
X39735	2320	008358322	M37	80250535	1008415	1953	H
X39735	2320	008358322	M37	80250539	1008373	1953	H

X39735	2320	008358322	M37	80250584	2438144	1953	H
X39735	2320	008358322	M37	80250648	2434471	1953	C
X39735	2320	008358322	M37	80250764	2438173	1953	C
X39735	2320	008358322	M37	80250894	1008485	1953	C
X39735	2320	008358322	M37	80250904	2438359	1953	H
X39735	2320	008358322	M37	80250937	1008506	1953	H
X39735	2320	008358322	M37	80251035	1008857	1953	H
X39735	2320	008358322	M37	80251049	1009095	1953	H
X39735	2320	008358322	M37	80251061	20100846	1953	H
X39735	2320	008358322	M37	80251106	1008663	1953	H
X39735	2320	008358322	M37	80251118	20100849	1953	H
X39735	2320	008358322	M37	80251121	1008482	1953	H
X39735	2320	008358322	M37	80251123	1008543	1953	H
X39735	2320	008358322	M37	80251143	20100855	1953	C
X39735	2320	008358322	M37	80251150	2438295	1953	H
X39735	2320	008358322	M37	80251193	1008552	1966	H
X39735	2320	008358322	M37	80251204	1008479	1953	C
X39735	2320	008358322	M37	80251218	20100848	1953	H
X39735	2320	008358322	M37	80251273	1008582	1953	H
X39735	2320	008358322	M37	80251364	1010086	1953	H
X39735	2320	008358322	M37	80251446	2442192	1953	C
X39735	2320	008358322	M37	80251601	1008567	1953	H
X39735	2320	008358322	M37	80251617	1008601	1953	H
X39735	2320	008358322	M37	80251687	1008644	1953	H
X39735	2320	008358322	M37	80251853	10008631	1953	C
X39735	2320	008358322	M37	80251860	3A4331	1953	C
X39735	2320	008358322	M37	80251898	3A4363	1953	H
X39735	2320	008358322	M37	80251993	1012074	1953	H
X39735	2320	008358322	M37	80252047	1008679	1953	H
X39735	2320	008358322	M37	80252173	3A8444	1953	H
X39735	2320	008358322	M37	80252207	2404830	1953	H
X39735	2320	008358322	M37	80252238	3A4249	1953	H
X39735	2320	008358322	M37	8025230	3A4386	1953	H
X39735	2320	008358322	M37	80252333	1012035	1953	H
X39735	2320	008358322	M37	80252381	2437781	1953	C
X39735	2320	008358322	M37	80252405	1008869	1953	C
X39735	2320	008358322	M37	80252427	NF0007	1953	H
X39735	2320	008358322	M37	80252439	3A8633	1953	C
X39735	2320	008358322	M37	80252448	2437735	1953	C
X39735	2320	008358322	M37	80252475	1008845	1953	H
X39735	2320	008358322	M37	80252495	2N008768	1953	H
X39735	2320	008358322	M37	80252573	2443187	1953	C
X39735	2320	008358322	M37	80252588	20100893	1953	H
X39735	2320	008358322	M37	80252634	2437840	1953	H
X39735	2320	008358322	M37	80252735	2437810	1953	H
X39735	2320	008358322	M37	80252751	1008842	1953	H
X39735	2320	008358322	M37	80252802	1008907	1953	H
X39735	2320	008358322	M37	80252958	3A8522	1953	H
X39735	2320	008358322	M37	80253011	3B2988	1953	C
X39735	2320	008358322	M37	80253017	2437865	1951	H
X39735	2320	008358322	M37	80253101	2443466	1953	C
X39735	2320	008358322	M37	80253166	NF0006	1953	H

X39735	2320	008358322	M37	80253243	2437871	1953	H
X39735	2320	008358322	M37	80253315	2438001	1953	H
X39735	2320	008358322	M37	80253373	1009101	1953	H
X39735	2320	008358322	M37	80253467	20100642	1953	H
X39735	2320	008358322	M37	80253497	1009002	1953	H
X39735	2320	008358322	M37	80253632	20100904	1953	H
X39735	2320	008358322	M37	80253670	3B3238	1953	H
X39735	2320	008358322	M37	80253825	1009232	1953	C
X39735	2320	008358322	M37	80253898	3B2984	1953	H
X39735	2320	008358322	M37	80254040	2448561	1953	H
X39735	2320	008358322	M37	80254260	1009110	1953	H
X39735	2320	008358322	M37	80254308	1009113	1953	H
X39735	2320	008358322	M37	80254455	1009134	1953	C
X39735	2320	008358322	M37	80254514	2439159	1953	H
X39735	2320	008358322	M37	80254520	3E7287	1953	C
X39735	2320	008358322	M37	80254663	3Z42353	1953	H
X39735	2320	008358322	M37	80254665	1009196	1953	C
X39735	2320	008358322	M37	80254754	1009233	1953	H
X39735	2320	008358322	M37	80254761	1009229	1952	H
X39735	2320	008358322	M37	80254842	1009306	1953	H
X39735	2320	008358322	M37	80254985	1009230	1952	H
X39735	2320	008358322	M37	80255002	1010746	1953	H
X39735	2320	008358322	M37	8025511	1009347	1952	H
X39735	2320	008358322	M37	80255119	1009339	1953	H
X39735	2320	008358322	M37	80255158	1010819	1953	H
X39735	2320	008358322	M37	802552013	3A8448	1953	C
X39735	2320	008358322	M37	80255284	1009479	1953	H
X39735	2320	008358322	M37	80255327	1008818	1953	C
X39735	2320	008358322	M37	80255370	1009445	1953	H
X39735	2320	008358322	M37	80255377	1009438	1953	H
X39735	2320	008358322	M37	80255439	1009577	1953	H
X39735	2320	008358322	M37	80255441	1009493	1953	C
X39735	2320	008358322	M37	802554846	20100948	1952	C
X39735	2320	008358322	M37	80255486	1009489	1953	H
X39735	2320	008358322	M37	80255493	1010891	1953	C
X39735	2320	008358322	M37	80255598	1009533	1953	C
X39735	2320	008358322	M37	80255627	1009918	1953	C
X39735	2320	008358322	M37	80255687	1009644	1953	H
X39735	2320	008358322	M37	80255700	1009602	1953	H
X39735	2320	008358322	M37	80255712	20100960	1953	H
X39735	2320	008358322	M37	80255731	1009598	1953	H
X39735	2320	008358322	M37	80255739	1009784	1953	H
X39735	2320	008358322	M37	80255744	1009596	1953	H
X39735	2320	008358322	M37	80255873	1009683	1953	H
X39735	2320	008358322	M37	80255875	1009482	1952	C
X39735	2320	008358322	M37	80255902	1009856	1953	H
X39735	2320	008358322	M37	80255925	1009749	1953	H
X39735	2320	008358322	M37	80255932	1009818	1953	H
X39735	2320	008358322	M37	80255935	1009756	1953	H
X39735	2320	008358322	M37	80255937	20100973	1953	C
X39735	2320	008358322	M37	80255961	1009737	1953	C
X39735	2320	008358322	M37	80256004	2439570	1953	H

X39735	2320	008358322	M37	80256031	1009759	1953	C
X39735	2320	008358322	M37	80256033	1009736	1953	C
X39735	2320	008358322	M37	80256039	1009778	1953	C
X39735	2320	008358322	M37	80256348	1009851	1953	C
X39735	2320	008358322	M37	80256378	1009861	1953	C
X39735	2320	008358322	M37	802564482	1009916	1953	H
X39735	2320	008358322	M37	80256465	21009891	1969	C
X39735	2320	008358322	M37	80256503	2439571	1953	H
X39735	2320	008358322	M37	80256505	3Z42853	1953	H
X39735	2320	008358322	M37	8025651	2382585	1952	H
X39735	2320	008358322	M37	80256532	3Z38853	1953	H
X39735	2320	008358322	M37	80256561	3B2585	1953	H
X39735	2320	008358322	M37	80256598	3C6915	1953	C
X39735	2320	008358322	M37	80256615	1010014	1953	H
X39735	2320	008358322	M37	80256661	3B2620	1953	H
X39735	2320	008358322	M37	80256713	2439735	1953	H
X39735	2320	008358322	M37	80256736	1009936	1953	C
X39735	2320	008358322	M37	80256821	20109964	1953	H
X39735	2320	008358322	M37	80256843	3B3517	1953	H
X39735	2320	008358322	M37	80256862	1010011	1953	C
X39735	2320	008358322	M37	80257065	1009971	1953	H
X39735	2320	008358322	M37	80257115	1010077	1953	H
X39735	2320	008358322	M37	80257158	1011008	1953	H
X39735	2320	008358322	M37	80257160	3A0544	1953	C
X39735	2320	008358322	M37	80257164	1010061	1953	C
X39735	2320	008358322	M37	80257166	1010082	1953	H
X39735	2320	008358322	M37	80257207	3A0545	1953	H
X39735	2320	008358322	M37	80257224	1010100	1953	H
X39735	2320	008358322	M37	80257226	1010074	1953	C
X39735	2320	008358322	M37	80257292	1011903	1953	H
X39735	2320	008358322	M37	80257368	1012023	1953	H
X39735	2320	008358322	M37	80257380	1012148	1953	H
X39735	2320	008358322	M37	80257396	1011889	1953	H
X39735	2320	008358322	M37	80257450	2439938	1953	C
X39735	2320	008358322	M37	80257466	1011954	1953	H
X39735	2320	008358322	M37	80257504	1011913	1953	H
X39735	2320	008358322	M37	80257575	2449728	1953	H
X39735	2320	008358322	M37	80257648	1011928	1953	H
X39735	2320	008358322	M37	80257663	1010122	1953	C
X39735	2320	008358322	M37	80257690	1011950	1953	C
X39735	2320	008358322	M37	80257707	1012021	1953	H
X39735	2320	008358322	M37	80257766	1012031	1953	H
X39735	2320	008358322	M37	80257887	1012032	1953	H
X39735	2320	008358322	M37	80257888	1012001	1953	C
X39735	2320	008358322	M37	80257922	1012015	1953	H
X39735	2320	008358322	M37	80257938	3A6672	1953	C
X39735	2320	008358322	M37	80257957	2440738	1953	H
X39735	2320	008358322	M37	8025803	1012441	1953	C
X39735	2320	008358322	M37	80258153	1012094	1953	H
X39735	2320	008358322	M37	80258216	244077	1953	H
X39735	2320	008358322	M37	80258233	1012122	1953	H
X39735	2320	008358322	M37	80258284	2446664	1953	C

X39735	2320	008358322	M37	80258326	2446599	1953	H
X39735	2320	008358322	M37	80258482	3B2825	1953	C
X39735	2320	008358322	M37	80258570	2440762	1953	H
X39735	2320	008358322	M37	80258630	2440779	1953	C
X39735	2320	008358322	M37	80258799	3B2843	1959	C
X39735	2320	008358322	M37	80258837	2446592	1954	C
X39735	2320	008358322	M37	80258972	3B2794	1954	C
X39735	2320	008358322	M37	80259064	3B2854	1971	H
X39735	2320	008358322	M37	80259116	2446703	1954	C
X39735	2320	008358322	M37	80259286	3B2796	1954	C
X39735	2320	008358322	M37	80259460	2446815	1954	H
X39735	2320	008358322	M37	80259473	2441445	1954	H
X39735	2320	008358322	M37	80259494	2440969	1954	C
X39735	2320	008358322	M37	80259534	2440992	1953	C
X39735	2320	008358322	M37	80259568	2441003	1954	C
X39735	2320	008358322	M37	80259571	2446875	1954	H
X39735	2320	008358322	M37	80259600	2446894	1954	C
X39735	2320	008358322	M37	80259834	2441247	1954	H
X39735	2320	008358322	M37	80259884	2441460	1954	H
X39735	2320	008358322	M37	80259895	2441329	1954	H
X39735	2320	008358322	M37	80259919	2441195	1954	C
X39735	2320	008358322	M37	80259923	2441201	1954	H
X39735	2320	008358322	M37	80259943	2441303	1954	H
X39735	2320	008358322	M37	80259999	2441720	1954	C
X39735	2320	008358322	M37	80260019	2441431	1954	H
X39735	2320	008358322	M37	80260054	2441342	1954	H
X39735	2320	008358322	M37	80260060	2443406	1954	H
X39735	2320	008358322	M37	80260064	2442036	1954	C
X39735	2320	008358322	M37	80260097	2441383	1954	H
X39735	2320	008358322	M37	80260201	2441357	1954	C
X39735	2320	008358322	M37	80260239	22141420	1954	H
X39735	2320	008358322	M37	80260251	2441493	1954	H
X39735	2320	008358322	M37	80260262	2442019	1954	C
X39735	2320	008358322	M37	80260264	2441466	1954	C
X39735	2320	008358322	M37	80260265	2441462	1954	H
X39735	2320	008358322	M37	80260365	2441730	1954	C
X39735	2320	008358322	M37	80260393	2441945	1954	H
X39735	2320	008358322	M37	80260413	2442058	1954	C
X39735	2320	008358322	M37	80260415	2441547	1954	C
X39735	2320	008358322	M37	8026042	2434477	1953	C
X39735	2320	008358322	M37	80260501	2441527	1954	C
X39735	2320	008358322	M37	80260532	2441550	1954	C
X39735	2320	008358322	M37	80260560	2442037	1954	H
X39735	2320	008358322	M37	802606	2441908	1952	C
X39735	2320	008358322	M37	80260640	2447145	1954	H
X39735	2320	008358322	M37	80260654	3B3615	1954	C
X39735	2320	008358322	M37	80260700	2447131	1954	H
X39735	2320	008358322	M37	80260701	2441647	1954	C
X39735	2320	008358322	M37	80260724	2441618	1954	H
X39735	2320	008358322	M37	80260730	2441685	1954	C
X39735	2320	008358322	M37	80260747	2441913	1954	C
X39735	2320	008358322	M37	80260761	2441699	1954	C

X39735	2320	008358322	M37	80260769	2441664	1954	C
X39735	2320	008358322	M37	80260775	2441645	1954	C
X39735	2320	008358322	M37	80260800	2441711	1954	C
X39735	2320	008358322	M37	80260809	2441653	1954	C
X39735	2320	008358322	M37	80260820	2441966	1954	H
X39735	2320	008358322	M37	80260846	2441696	1954	C
X39735	2320	008358322	M37	80260872	2441702	1954	C
X39735	2320	008358322	M37	80260878	2441735	1954	C
X39735	2320	008358322	M37	80260927	2441952	1954	H
X39735	2320	008358322	M37	80260935	2442802	1954	H
X39735	2320	008358322	M37	80260960	2441959	1954	H
X39735	2320	008358322	M37	80260971	2442012	1954	H
X39735	2320	008358322	M37	80261008	2442071	1954	H
X39735	2320	008358322	M37	80261014	2442681	1954	C
X39735	2320	008358322	M37	80261019	2441891	1954	H
X39735	2320	008358322	M37	80261033	2441990	1954	H
X39735	2320	008358322	M37	80261069	2441973	1954	C
X39735	2320	008358322	M37	80261076	2441866	1954	C
X39735	2320	008358322	M37	80261099	2442137	1954	C
X39735	2320	008358322	M37	80261117	2441874	1954	H
X39735	2320	008358322	M37	80261120	2443075	1954	H
X39735	2320	008358322	M37	80261123	2441931	1954	H
X39735	2320	008358322	M37	80261146	2441903	1954	H
X39735	2320	008358322	M37	80261149	2441922	1954	C
X39735	2320	008358322	M37	80261154	2441905	1954	H
X39735	2320	008358322	M37	80261169	2442038	1954	C
X39735	2320	008358322	M37	80261206	2441940	1954	H
X39735	2320	008358322	M37	80261220	2442054	1954	C
X39735	2320	008358322	M37	80261230	2442267	1954	C
X39735	2320	008358322	M37	80261251	2442031	1954	C
X39735	2320	008358322	M37	80261254	2442014	1954	C
X39735	2320	008358322	M37	8026126	2442026	1954	C
X39735	2320	008358322	M37	80261262	2442172	1954	H
X39735	2320	008358322	M37	80261269	2442210	1954	C
X39735	2320	008358322	M37	80261270		1954	C
X39735	2320	008358322	M37	80261283	2442481	1954	C
X39735	2320	008358322	M37	80261297	2442044	1954	H
X39735	2320	008358322	M37	80261309	2442052	1954	C
X39735	2320	008358322	M37	80261311	2442944	1954	C
X39735	2320	008358322	M37	80261347	2442184	1954	H
X39735	2320	008358322	M37	80261355	2442076	1954	C
X39735	2320	008358322	M37	80261356	2442131	1954	C
X39735	2320	008358322	M37	80261375	2442075	1954	C
X39735	2320	008358322	M37	80261376	2442073	1954	C
X39735	2320	008358322	M37	80261379	2442171	1954	H
X39735	2320	008358322	M37	80261391	2442096	1954	C
X39735	2320	008358322	M37	80261412	1008519	1954	C
X39735	2320	008358322	M37	80261507	2442257	1954	C
X39735	2320	008358322	M37	80261518	2442426	1954	C
X39735	2320	008358322	M37	80261520	2442273	1954	H
X39735	2320	008358322	M37	80261529	2442329	1954	H
X39735	2320	008358322	M37	80261530	2442635	1954	H

X39735	2320	008358322	M37	80261553	2442365	1954	H
X39735	2320	008358322	M37	80261556	2442472	1954	C
X39735	2320	008358322	M37	80261558	2442201	1954	H
X39735	2320	008358322	M37	80261655	2442319	1954	H
X39735	2320	008358322	M37	80261705	2442317	1954	C
X39735	2320	008358322	M37	80261706	2442483	1954	C
X39735	2320	008358322	M37	80261708	2442691	1954	C
X39735	2320	008358322	M37	80261730	2442435	1954	H
X39735	2320	008358322	M37	80261744	2448853	1954	C
X39735	2320	008358322	M37	80261745	2442596	1954	H
X39735	2320	008358322	M37	80261754	2442615	1954	C
X39735	2320	008358322	M37	80261770	2442391	1954	C
X39735	2320	008358322	M37	80261787	2442410	1954	C
X39735	2320	008358322	M37	80261795	2442349	1954	H
X39735	2320	008358322	M37	80261799	2442542	1954	H
X39735	2320	008358322	M37	80261812	2442408	1954	C
X39735	2320	008358322	M37	80261841	2442440	1954	H
X39735	2320	008358322	M37	80261857	2442512	1954	C
X39735	2320	008358322	M37	80261862	2442507	1954	C
X39735	2320	008358322	M37	80261869	2442476	1954	C
X39735	2320	008358322	M37	80261874	2442499	1954	C
X39735	2320	008358322	M37	80261876	2442523	1954	C
X39735	2320	008358322	M37	80261881	2442439	1954	C
X39735	2320	008358322	M37	80261893	2442796	1954	H
X39735	2320	008358322	M37	80261909	2442451	1954	H
X39735	2320	008358322	M37	80261916	2442474	1954	C
X39735	2320	008358322	M37	80261924	2442448	1954	C
X39735	2320	008358322	M37	80261933	2442678	1954	H
X39735	2320	008358322	M37	80261937	2442458	1954	C
X39735	2320	008358322	M37	80261942	2442720	1954	H
X39735	2320	008358322	M37	80261944	2442477	1954	C
X39735	2320	008358322	M37	80261949	2442554	1954	C
X39735	2320	008358322	M37	80261955	2442496	1954	C
X39735	2320	008358322	M37	80261963	2442478	1954	C
X39735	2320	008358322	M37	80261986	2442509	1954	C
X39735	2320	008358322	M37	80261988	2442498	1954	C
X39735	2320	008358322	M37	80261992	2442486	1954	C
X39735	2320	008358322	M37	80261993	2442487	1954	C
X39735	2320	008358322	M37	80262011	2442548	1954	C
X39735	2320	008358322	M37	80262044	2442915	1954	H
X39735	2320	008358322	M37	80262054	2442535	1954	H
X39735	2320	008358322	M37	80262070	2442622	1954	C
X39735	2320	008358322	M37	80262073	2442571	1954	C
X39735	2320	008358322	M37	80262085	2442654	1954	C
X39735	2320	008358322	M37	80262097	2442587	1954	H
X39735	2320	008358322	M37	80262123	2442755	1954	C
X39735	2320	008358322	M37	80262194	2442907	1954	C
X39735	2320	008358322	M37	80262200	2442721	1954	H
X39735	2320	008358322	M37	80262208	2442954	1954	C
X39735	2320	008358322	M37	80262272	2442738	1954	H
X39735	2320	008358322	M37	80262276	2443270	1954	C
X39735	2320	008358322	M37	80262299	2442797	1954	H

X39735	2320	008358322	M37	80262311	2442948	1954	C
X39735	2320	008358322	M37	80262322	2442804	1953	C
X39735	2320	008358322	M37	80262324	2442742	1954	H
X39735	2320	008358322	M37	80262337	2442876	1954	C
X39735	2320	008358322	M37	80262340	2442774	1954	H
X39735	2320	008358322	M37	80262347	2442937	1954	C
X39735	2320	008358322	M37	80262351	2442963	1954	C
X39735	2320	008358322	M37	80262355	2442939	1954	C
X39735	2320	008358322	M37	80262356	2442966	1954	C
X39735	2320	008358322	M37	80262373	2442918	1954	C
X39735	2320	008358322	M37	80262409	2442830	1954	C
X39735	2320	008358322	M37	80262428	2442981	1954	C
X39735	2320	008358322	M37	80262429	2442906	1954	H
X39735	2320	008358322	M37	8026243	2443425	1954	C
X39735	2320	008358322	M37	80262454	2442869	1954	H
X39735	2320	008358322	M37	80262470	2442878	1954	C
X39735	2320	008358322	M37	80262473	2443768	1954	H
X39735	2320	008358322	M37	802624771	2442909	1954	C
X39735	2320	008358322	M37	80262488	2442902	1954	H
X39735	2320	008358322	M37	80262489	2443048	1954	C
X39735	2320	008358322	M37	80262500	2442951	1954	C
X39735	2320	008358322	M37	80262514	2443573	1954	C
X39735	2320	008358322	M37	80262521	2442987	1954	C
X39735	2320	008358322	M37	80262533	2443058	1954	C
X39735	2320	008358322	M37	80262544	2442929	1954	C
X39735	2320	008358322	M37	80262553	2442959	1954	C
X39735	2320	008358322	M37	80262554	2443036	1954	C
X39735	2320	008358322	M37	80262557	2443179	1954	H
X39735	2320	008358322	M37	80262559	2442993	1954	C
X39735	2320	008358322	M37	80262565	2442971	1954	C
X39735	2320	008358322	M37	80262610	2443477	1954	H
X39735	2320	008358322	M37	80262621	2443118	1954	H
X39735	2320	008358322	M37	8026267	2443183	1954	C
X39735	2320	008358322	M37	80262685	2443241	1954	C
X39735	2320	008358322	M37	80262707	2443122	1954	H
X39735	2320	008358322	M37	80262714	2442854	1954	H
X39735	2320	008358322	M37	80262722	2443100	1954	H
X39735	2320	008358322	M37	80262725	2443077	1952	C
X39735	2320	008358322	M37	80262727	2443083	1954	H
X39735	2320	008358322	M37	80262742	2443198	1954	C
X39735	2320	008358322	M37	80262811	2443243	1954	C
X39735	2320	008358322	M37	80262831	2443618	1954	H
X39735	2320	008358322	M37	80262837	2443207	1954	C
X39735	2320	008358322	M37	80262864	2443194	1954	C
X39735	2320	008358322	M37	80262865	2443257	1954	C
X39735	2320	008358322	M37	80262869	2443648	1954	C
X39735	2320	008358322	M37	80262870	2443275	1954	C
X39735	2320	008358322	M37	80262890	2443783	1954	C
X39735	2320	008358322	M37	80262894	2443403	1954	C
X39735	2320	008358322	M37	80262897	2443675	1954	C
X39735	2320	008358322	M37	80262912	2443390	1954	H
X39735	2320	008358322	M37	80262933	2443413	1954	C



X39735	2320	008358322	M37	80262937	2443389	1954	H
X39735	2320	008358322	M37	80262954	2443438	1954	C
X39735	2320	008358322	M37	80262970	2443303	1954	H
X39735	2320	008358322	M37	80262987	2443478	1954	H
X39735	2320	008358322	M37	80262998	2443570	1954	H
X39735	2320	008358322	M37	80263001	2443611	1954	H
X39735	2320	008358322	M37	80263011	2443326	1954	C
X39735	2320	008358322	M37	80263037	2443453	1954	H
X39735	2320	008358322	M37	80263040	2443400	1954	H
X39735	2320	008358322	M37	80263043	2443369	1954	H
X39735	2320	008358322	M37	80263059	2443399	1954	H
X39735	2320	008358322	M37	80263069	2443437	1954	C
X39735	2320	008358322	M37	80263089	2443496	1954	C
X39735	2320	008358322	M37	80263105	2443743	1954	H
X39735	2320	008358322	M37	80263193	2442679	1954	C
X39735	2320	008358322	M37	80263205	2443683	1954	H
X39735	2320	008358322	M37	802632202	2443773	1954	H
X39735	2320	008358322	M37	80263248	2443595	1954	C
X39735	2320	008358322	M37	80263258	2384304	1954	H
X39735	2320	008358322	M37	80263259	2443612	1954	H
X39735	2320	008358322	M37	8026325H	2443673	1954	C
X39735	2320	008358322	M37	80263269	2443632	1954	H
X39735	2320	008358322	M37	80263294	2443814	1954	H
X39735	2320	008358322	M37	80263340	2443761	1954	H
X39735	2320	008358322	M37	80263375	2443708	1954	H
X39735	2320	008358322	M37	80263380	2443653	1954	C
X39735	2320	008358322	M37	80263386	2443712	1954	H
X39735	2320	008358322	M37	80263405	2443763	1954	C
X39735	2320	008358322	M37	80263411	2443655	1954	C
X39735	2320	008358322	M37	80263429	2443765	1954	H
X39735	2320	008358322	M37	80263448	2443749	1954	C
X39735	2320	008358322	M37	80263462	2443704	1954	H
X39735	2320	008358322	M37	80263482	2443846	1954	C
X39735	2320	008358322	M37	80263484	2443870	1954	H
X39735	2320	008358322	M37	80263520	2443745	1954	C
X39735	2320	008358322	M37	80263526	2406506	1954	C
X39735	2320	008358322	M37	80263588	2443832	1954	H
X39735	2320	008358322	M37	80263593	2443825	1954	C
X39735	2320	008358322	M37	80263612	2443810	1954	C
X39735	2320	008358322	M37	80263614	2443971	1954	H
X39735	2320	008358322	M37	80263755	2450630	1954	H
X39735	2320	008358322	M37	80263834	2441895	1954	H
X39735	2320	008358322	M37	80263956	2444078	1954	C
X39735	2320	008358322	M37	802661895	2442688	1954	H
X39735	2320	008358322	M37	8026651	2443076	1954	H
X39735	2320	008358322	M37	8026791	2443692	1954	H
X39735	2320	008358322	M37	8026991	2441914	1954	H
X39735	2320	008358322	M37	80281344	2442065	1954	C
X39735	2320	008358322	M37	8047542	2434509	1952	H
X39735	2320	008358322	M37	8057664	1012401	1953	C
X39735	2320	008358322	M37	80612116	2401590	1951	C
X39735	2320	008358322	M37	8062027	2442599	1972	H

X39735	2320	008358322	M37	80640785	20955631	1954	C
X39735	2320	008358322	M37	80660786	2447123	1954	H
X39735	2320	008358322	M37	80755135	20101082	1954	C
X39735	2320	008358322	M37	80757879	2437862	1954	H
X39735	2320	008358322	M37	80760046	2441298	1954	H
X39735	2320	008358322	M37	80763394	2443718	1954	C
X39735	2320	008358322	M37	8098342	2410449	1952	H
X39735	2320	008358322	M37	8103003	2402719	1953	C
X39735	2320	008358322	M37	820261892	2442434	1954	H
X39735	2320	008358322	M37	8232	2412694	1951	H
X39735	2320	008358322	M37	8262737	2443072	1954	C
X39735	2320	008358322	M37	8358227	20941255	1954	C
X39735	2320	008358322	M37	8358322	2402331	1952	H
X39735	2320	008358322	M37	86041300	2426562	1952	C
X39735	2320	008358322	M37	8756161	2437577	1953	C
X39735	2320	008358322	M37	8927	2401196	1951	C
X39735	2320	008358322	M37	8D261448	2442136	1952	C
X39735	2320	008358322	M37	9168	2441016	1951	C
X39735	2320	008358322	M37	BE4S073871	NF000F	1952	H
X39735	2320	008358322	M37	L2452180	3A5483	1953	H
X39735	2320	008358322	M37	L24526942	2431224	1952	C
X39735	2320	008358322	M37	L2457492	3B0883	1952	C
X39735	2320	008358322	M37	P0051213	3A8449	1953	C
X39735	2320	008358322	M37	US241803	2412917	1962	H